



Approved CR

IAA Las Vegas  
3225 South Hollywood Blvd  
Branch No 152  
Las Vegas, NV 89122  
(702) 565-8795/(702) 564-6553  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD  
FOCUS**  
Bodystyle/Series: **4 Door Sedan  
SE**  
Color: **Silver**  
Mileage: **49,400  
(Verified)**  
Turn-in Mileage: **-**  
VIN: **1FADP3F21JL327469**  
Work Order/  
Stock Number: **46407948**  
Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalesupport@gsa.gov**  
Client Stock #: **G131643V**  
Vehicle Grade : **Grade 3.7**  
Remarks: **-**  
Announcements: **-**  
Certification : **-**  
Req. Prev. Repair **-**  
Order:



Drivable: Yes

### Equipment


|                        |                       |                 |                   |
|------------------------|-----------------------|-----------------|-------------------|
| Transmission:          | -                     | A/C:            | No                |
| Engine:                | 4-Cylinder Gas        | Cruise Control: | Yes               |
| Engine Size:           | 2 L                   | Pwr Steering:   | Yes               |
| Roof:                  | Hard Top              | Pwr Locks:      | Yes               |
| Radio:                 | -                     | Pwr Windows     | Yes               |
| Interior - Type/Color: | Cloth Interior /BLACK | Rear Defroster: | Yes               |
| Airbag:                | Driver Side Air Bag   | Tilt Steering:  | Yes               |
| Seats:                 | 5th                   | Drive Type:     | Front Wheel Drive |
| Seat Count:            | -                     | Brakes:         | Air Brakes        |

## Equipment

### Additional Equipment:

|                                    |                                    |                                     |
|------------------------------------|------------------------------------|-------------------------------------|
| Car Tire Size - LF 215 / 55 R 16   | Car Tire Size - LR 215 / 55 R 16   | Car Tire Size - RR 215 / 55 R 16    |
| Car Tire Size - RF 215 / 55 R 16   | LF Tires - 6/32 inch               | LR Tires - 8/32 inch                |
| RF Tires - 6/32 inch               | RR Tires - 7/32 inch               | Tire Brand - Front Left - SUREDRIVE |
| Tire Brand - Front Right - SENTURY | Tire Brand - Rear Left - SUREDRIVE | Tire Brand - Rear Right - SUREDRIVE |
| Tire Model - RR - All-Season       | Tire Model - RF - Sentury Touring  | Tire Model - LR - All-Season        |
| Tire Model - LF - All-Season       |                                    |                                     |

## Non Chargeable Damages

| Photo                                                                               | Item                   | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|------------------------|------------|--------|----------|
|    | Engine                 | Photo Only | -      | -        |
|    | Photo - Vin/Id Sticker | Photo Only | -      | -        |
|   | Front Cover Center     | Photo Only | -      | -        |
|  | Right Side Panel       | Photo Only | -      | -        |
|  | Left Side Panel        | Photo Only | -      | -        |
|  | Instrument Panel       | Photo Only | -      | -        |
|  | Rear Bumper            | Photo Only | -      | -        |
|  | Right Front Fender     | Photo Only | -      | -        |

### Non Chargeable Damages

| Photo                                                                               | Item                    | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|-------------------------|------------|--------|----------|
|    | Left Front Fender       | Photo Only | -      | -        |
|    | Left Rear Bumper/Cover  | Photo Only | -      | -        |
|    | Right Rear Bumper/Cover | Photo Only | -      | -        |
|    | Photo - Dash            | Photo Only | -      | -        |
|    | Extra Photo 1           | Photo Only | -      | -        |
|   | Odometer                | Photo Only | -      | -        |
|  | Rear Seats              | Photo Only | -      | -        |
|  | Keys                    | Photo Only | -      | -        |

### Chargeable Damages

| Photo                                                                               | Item           | Damage | Action | Severity        |
|-------------------------------------------------------------------------------------|----------------|--------|--------|-----------------|
|  | Left Head Lamp | Faded  | -      | Repair Required |

### Chargeable Damages

| Photo                                                                               | Item              | Damage                   | Action | Severity        |
|-------------------------------------------------------------------------------------|-------------------|--------------------------|--------|-----------------|
|    | Right Head Lamp   | Faded                    | -      | Repair Required |
|    | Right Front Wheel | Curb Rash                | -      | 3 To 4 Inches   |
|    | Left Rear Wheel   | Curb Rash                | -      | 1 To 2 Inches   |
|   | Left Front Wheel  | Curb Rash                | -      | 1 To 2 Inches   |
|  | Front Bumper      | Multiple Scratches Heavy | -      | 3               |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.