



Approved CR

America's Auto Auction - Pensacola, Inc
6615 Mobile Highway
Pensacola, FL 32526-1264
850-972-8601/(850) 944-8482
Della.Smith@AmericasAutoAuction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 FORD
EXPLORER**
**4 Door Sport
Utility**
Bodystyle/Series: **Vehicle BASE
4WD 4D SUV
4WD**
Color: **SILVER**
Mileage: **46,881
(Verified, 6
digits)**
Turn-in Mileage: **-**
VIN: **1FM5K8B82HGE14171**
Work Order/
Stock Number: **000355318**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G625092U**
Vehicle Grade : **Grade 4.3**
Remarks: **REMOVAL
OF POLICE
LIGHTS/ PA
SYSTEM**
Announcements: **-**
Certification : **Not Certified**
Req. Prev. Repair **-**
Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM CD	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BEIGE	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	Power	Drive Type:	4-Wheel Drive

Equipment

Seat Count:	-	Brakes:	Power Brakes
Additional Equipment:			
3rd Row Seat	4 Wheel Drive	4 Wheel Drive	
4th Passenger Door	ABS Brakes	Air Conditioning	
Automatic Headlights	Auxiliary Pwr Outlet	Bluetooth Connection	
Brake Assist System	CD Player	Car Tire Size - LR tire size P245/60HR18	
Car Tire Size - RF tire size P245/60HR18	Car Tire Size - RR tire size P245/60HR18	Car Tire Size - LF tire size P245/60HR18	
Child Safety Locks	Cruise Control	Cylinders - 6	
Daytime Running Lights	Driver Air Bag	Empty Weight - 4629 lb	
Engine Immobilizer	Floor Mats	Independent Climate Control	
Intermittent Wipers	Keyless Entry	LED Headlights	
LF Tires - 8/32 inch	LR Tires - 7/32 inch	MP3 Radio	
Master Key - 1key(s)	Motor Fuel Type - Gas	Pass-Through Rear Seat	
Pass. Air Bag	Power Brakes	Power Driver Seat	
Power Lock	Power Mirrors	Power Steering	
Power Windows	Privacy Glass	RF Tires - 7/32 inch	
RR Tires - 7/32 inch	Rear AC	Rear Defrost	
Rear Spoiler	Reverse Camera	Seat Trim - Cloth	
Side Airbags - Front	Steering Wheel Audio Control	Telematics	
Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg Michelin	Tire Brand - Front Right - RF tire mfg Michelin	
Tire Brand - Rear Left - LR tire mfg Michelin	Tire Brand - Rear Right - RR tire mfg Michelin	Tire Pressure Monitor System	
Tow Hitch	Traction Control	Transmission - Automatic Transmission w/ Overdrive	
Trip Computer	Wheels Front Left - Aluminium	Wheels Front Right - Aluminium	
Wheels Rear Left - Aluminium	Wheels Rear Right - Aluminium		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown



Non Chargeable Damages







Photo	Item	Damage	Action	Severity
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Extra Photo 6	Photo Only	Estimate Only	Unknown
	Extra Photo 7	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	3rd Row Seat	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper/Cover	Chipped	Report	5
	Hood	Chipped	Report	5
	Left Sunvisor	Broken	Report	Replacement Required

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Door	Multiple Scratches Light	Report	6
	Left Front Fender	Chipped	Report	2
	Left Rear Door	Multiple Scratches Light	Report	6
	Right Qtr Panel	Multiple Scratches Light	Report	6
	Rear Bumper/Cover	Chipped	Report	5
	Right Front Door	Multiple Scratches Light	Report	6
	Right Front Fender	Multiple Scratches Light	Report	6
	Right Rear Door	Multiple Scratches Light	Report	6
[no photo]	Oil	Low Fluid	Report	Unacceptable
	Left Qtr Panel	Multiple Scratches Light	Report	6

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.