



Approved CR

IAA Kansas City
2663 S 88th Street
Branch No 527
Kansas City, KS 66111
(913) 422-9303/(913) 422-7421
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016 FORD
F-450**
Bodystyle/Series: **Crew Cab XL**
Color: **White**
Mileage: **90,636
(Verified)**
Turn-in Mileage: **-**
VIN: **1FT8W4DT7GEC64147**
Work Order/
Stock Number: **46438233**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G710163S**
Vehicle Grade : **Grade 3.9**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RF 225 / 70 R 19.5	Car Tire Size - LR 225 / 70 R 19.5	Car Tire Size - RR 225 / 70 R 19.5
Car Tire Size - LF 225 / 70 R 19.5	LF Tires - 15/32 inch	LR Tires - 4/32 inch
RF Tires - 15/32 inch	RR Tires - 5/32 inch	Tire Brand - Front Left - HERCULES
Tire Brand - Front Right - HERCULES	Tire Brand - Rear Left - HERCULES	Tire Brand - Rear Right - HERCULES
Tire Model - LF - Strong Guard H-Ra	Tire Model - LR - Strong Guard H-Ra	Tire Model - RF - Strong Guard H-Ra
Tire Model - RR - Strong Guard H-Ra		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Seat Cushion	Stained	-	Permanent
	Right Qtr Flare	Heavy Scratch	-	1 To 2 Inches
	Right Head Lamp	Faded	-	Repair Required
	Left Head Lamp	Faded	-	Repair Required

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	1 To 2 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.