Approved CR

IAA Metro DC
14149 Brandywine Rd
Brandywine, MD 20613
(301) 372-8876/(301) 372-8285
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2020 DODGE DURANGO**
Bodystyle/Series:	**Sport Utility Vehicle PURSUIT AWD**
Color:	**Black**
Mileage:	**95,049 (Verified)**
Turn-in Mileage:	-
VIN:	**1C4RDJFGXLC308298**
Work Order/ Stock Number:	**46480073**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G626118X**
Vehicle Grade :	**Grade 3.2**
Remarks:	-
Announcements:	• Warning light on check IAA OBD11 REPORT FOR DETAILS • Prior police
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Leather/Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**

Equipment

Seats:	**Bench**	Drive Type:	**All Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Additional Equipment:

Car Tire Size - LF 265 / 60 R 18	Car Tire Size - LR 265 / 60 R 18	Car Tire Size - RR 265 / 60 R 18
Car Tire Size - RF 265 / 60 R 18	LF Tires - 7/32 inch	LR Tires - 7/32 inch
RF Tires - 7/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - RF - Assurance Fuel Max	Tire Model - LR - Assurance Fuel Max	Tire Model - LF - Assurance Fuel Max
Tire Model - RR - Assurance Fuel Max		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Center Console	Aftermarket	-	Acceptable
	Led Flashlight	Aftermarket	-	Acceptable
	Aftermarket Accessory	Aftermarket	-	Acceptable
	Warning Light - Engine	On	-	Unacceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Drip Rail	Hole(S)	-	1/2 To 1 Inch
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Head Lamp	Faded	-	Repair Required
	Right Head Lamp	Faded	-	Repair Required
	Left Front Seat Cushion	Torn	-	3 To 4 Inches
	Left Front Wheel	Curb Rash	-	6 To 7 Inches
	Overall Vehicle	De-Identify	-	Removal Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	1/2 To 1 Inch
	Front Bumper	Heavy Scratch	-	1 To 2 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.