Approved CR

America`s Auto Auction - Pensacola, Inc
6615 Mobile Highway
Pensacola, FL 32526-1264
850-972-8601/(850) 944-8482
Della.Smith@AmericasAutoAuction.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2019 HYUNDAI ELANTRA**
Bodystyle/Series:	**4 Door Sedan SE 4D SEDAN AT**
Color:	**SILVER**
Mileage:	**45,159 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**5NPD74LF9KH487158**
Work Order/ Stock Number:	**000356262**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	-
Vehicle Grade :	**Grade 4.5**
Remarks:	-
Announcements:	-
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**2 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	-	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Equipment


Additional Equipment:

ABS Brakes	Air Conditioning	Bluetooth Connection
Brake Assist System	Car Tire Size - RR tire size P195/65TR15	Car Tire Size - LF tire size P195/65TR15
Car Tire Size - RF tire size P195/65TR15	Car Tire Size - LR tire size P195/65TR15	Child Safety Locks
Cruise Control	Cylinders - 4	Daytime Running Lights
Driver Air Bag	Empty Weight - 2844 lb	Floor Mats
Front Wheel Drive	Front Wheel Drive	Intermittent Wipers
Keyless Entry	LF Tires - 9/32 inch	LR Tires - 5/32 inch
MP3 Radio	Master Key - 1key(s)	Motor Fuel Type - Gas
Pass-Through Rear Seat	Pass. Air Bag	Power Brakes
Power Lock	Power Mirrors	Power Steering
Power Windows	RF Tires - 9/32 inch	RR Tires - 5/32 inch
Rear Defrost	Remote Trunk Release	Reverse Camera
Seat Trim - Cloth	Security System	Side Airbags - Front
Spare Tire	Steering Wheel Audio Control	Stereo - AM/FM Radio
Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg Ironman	Tire Brand - Front Right - RF tire mfg Ironman
Tire Brand - Rear Left - LR tire mfg Nexen	Tire Brand - Rear Right - RR tire mfg Nexen	Tire Pressure Monitor System
Traction Control	Transmission - Automatic Transmission	Trip Computer
Wheels Front Left - Aluminium	Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium
Wheels Rear Right - Aluminium		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown




Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Deck Lid	Multiple Scratches Light	Report	6
	Front Bumper/Cover	Multiple Scratches Light	Report	6
	Left Front Door	Multiple Scratches Light	Report	6
	Left Front Seat	Stained	Report	Permanent
	Right Front Seat	Stained	Report	Permanent
	Right Rear Door	Multiple Scratches Light	Report	6
	Seat Center Rear	Stained	Report	Permanent
[no photo]	Left Rear Seat	Stained	Report	Permanent
[no photo]	Right Rear Seat	Stained	Report	Permanent
[no photo]	Oil	Low Fluid	Report	Unacceptable

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.