Approved CR

IAA Savannah
348 Commerce Dr.
Branch No 704
Rincon, GA 31326
(912) 826-1219/(912) 826-1387
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2021 DODGE CHARGER**
Bodystyle/Series:	**4 Door Sedan SXT RWD**
Color:	**Silver**
Mileage:	**79,244 (Verified)**
Turn-in Mileage:	-
VIN:	**2C3CDXBG9MH621537**
Work Order/ Stock Number:	**46449520**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G110385Y**
Vehicle Grade :	**Grade 4.1**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Air Brakes**

Equipment


Additional Equipment:

Car Tire Size - RR 215 / 65 R 17	Car Tire Size - RF 215 / 65 R 17	Car Tire Size - LF 215 / 65 R 17
Car Tire Size - LR 215 / 65 R 17	LF Tires - 8/32 inch	LR Tires - 8/32 inch
RF Tires - 6/32 inch	RR Tires - 6/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - LF - Assurance	Tire Model - LR - Assurance	Tire Model - RF - Assurance
Tire Model - RR - Assurance		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Warning - Tire Pressure	On	-	Unacceptable
	Deck Lid	Light Scratch	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Enviro Paint Damage	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.