



Approved CR

Central Auto Auction
185 Welton St.
Hamden, CT 06517
203-787-2277/203-787-6564
elise@centralaa.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016 RAM
5500
CHASSIS**

Bodystyle/Series: **2 Door
Pickup Truck**

Color: **WHITE**

Mileage: **9,923
(Verified)**

Turn-in Mileage: **-**

VIN: **3C7WRNBJ6GG139447**

Work Order/
Stock Number: **0171578**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**

Client Stock #: **710340X**

Vehicle Grade : **Grade 2.5**

Remarks: **-**

Announcements:

**• BED HAS
RUST**

Certification : **Not Certified**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

As Is 100K Miles: NO

Equipment

Transmission:	AutoStick	A/C:	Yes
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.4 L	Pwr Steering:	Yes
Roof:	-	Pwr Locks:	No
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Leather Interior /GRAY	Rear Defroster:	Yes
Airbag:	Dual and Side Airbags	Tilt Steering:	Yes
Seats:	-	Drive Type:	4-Wheel Drive
Seat Count:	3	Brakes:	Power Brakes

Equipment

Additional Equipment:

4 Wheel Drive	Car LF Tires - 5/32 inch	Car LR Tires - 5/32 inch
Car RF Tires - 5/32 inch	Car RR Tires - 5/32 inch	Cylinders - 8
Ignition Key - 1key(s)	LF Tires - 5/32 inch	LR Tires - 5/32 inch
Misc. Special Features - Back Up Sensor, Curtain Airbags, Side Airbags, Key - Ignition	RF Tires - 5/32 inch	RR Tires - 5/32 inch
Steering Wheel Audio Control	Tire LF - 5/32 inch	Tire RF - 5/32 inch
Tire Rating Front Left - AVERAGE	Tire Rating Front Right - AVERAGE	Tire Rating Rear Left - AVERAGE
Tire Rating Rear Right - AVERAGE	Trip Computer	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Extra Photo 8	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Tailgate	Dent(S) W/ Paint Dmg	-	3 To 4 Inches
	Rear Bumper	Dent(S) W/No Paint Dmg	-	3 To 4 Inches
	Left Rear Wheel	Bent	-	Replacement Required
	Left Bed Side	Rust	-	> 12 Inches
	Left Running Board	Loose	-	Repair Required
	Left Front Door	Chipped	-	10 Or More
	Front Bumper	Multiple Scratches Heavy	-	5
	Right Bed Side	Rust	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.