Approved CR

IAA Fremont
6700 Stevenson Blvd
Branch No 334
Fremont, CA 94538
(510) 668-1665/(510) 668-0106
WHOLESALE ASSESSMENT ONLY



| | |
|---|---|
| Make/Model: | **2019 HYUNDAI IONIQ HYBRID** |
| Bodystyle/Series: | **4 Door Hatch Back BLUE** |
| Color: | **White** |
| Mileage: | **89,285 (Verified)** |
| Turn-in Mileage: | - |
| VIN: | **KMHC65LC3KU107646** |
| Work Order/ Stock Number: | **46332372** |
| Customer: | GSA Fleet Vehicle Sales<br>1800 F Street NW<br>Washington, DC 20405<br>fleetsalessupport@gsa.gov |
| Client Stock #: | **G13-3524V** |
| Vehicle Grade : | **Grade 3.0** |
| Remarks: | - |
| Announcements: | - |
| Certification : | - |
| Req. Prev. Repair Order: | - |

Drivable: Yes

## Equipment

| | | | |
|---|---|---|---|
| Transmission: | - | A/C: | **No** |
| Engine: | **4-Cylinder Hybrid** | Cruise Control: | **Yes** |
| Engine Size: | **1.6 L** | Pwr Steering: | **Yes** |
| Roof: | **Hard Top** | Pwr Locks: | **Yes** |
| Radio: | - | Pwr Windows | **Yes** |
| Interior - Type/Color: | **Cloth Interior /GRAY** | Rear Defroster: | **Yes** |
| Airbag: | **Driver Side Air Bag** | Tilt Steering: | **Yes** |
| Seats: | **Buckets** | Drive Type: | **Front Wheel Drive** |
| Seat Count: | - | Brakes: | **Anti Lock Brakes** |

## Equipment


Additional Equipment:

| | | |
|---|---|---|
| Car Tire Size - LF 195 / 65 R 15 | Car Tire Size - LR 195 / 65 R 15 | Car Tire Size - RR 195 / 65 R 15 |
| Car Tire Size - RF 195 / 65 R 15 | LF Tires - 5/32 inch | LR Tires - 8/32 inch |
| RF Tires - 8/32 inch | RR Tires - 7/32 inch | Tire Brand - Front Left - MICHELIN |
| Tire Brand - Front Right - MICHELIN | Tire Brand - Rear Left - MICHELIN | Tire Brand - Rear Right - MICHELIN |
| Tire Model - RR - Defender T + H | Tire Model - RF - Defender T + H | Tire Model - LR - Defender T + H |
| Tire Model - LF - Defender T + H | | |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Front Cover Center | Photo Only | - | - |
|  | Right Side Panel | Photo Only | - | - |
|  | Left Side Panel | Photo Only | - | - |
|  | Instrument Panel | Photo Only | - | - |
|  | Rear Bumper | Photo Only | - | - |
|  | Extra Photo 2 | Photo Only | - | - |
|  | Extra Photo 3 | Photo Only | - | - |
|  | Right Front Fender | Photo Only | - | - |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Extra Photo 4 | Photo Only | - | - |
|  | Extra Photo 5 | Photo Only | - | - |
|  | Extra Photo 6 | Photo Only | - | - |
|  | Left Front Fender | Photo Only | - | - |
|  | Left Rear Bumper/Cover | Photo Only | - | - |
|  | Right Rear Bumper/Cover | Photo Only | - | - |
|  | Photo - Dash | Photo Only | - | - |
|  | Extra Photo 1 | Photo Only | - | - |
|  | Odometer | Photo Only | - | - |
|  | Rear Seats | Photo Only | - | - |
|  | Keys | Photo Only | - | - |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Photo - Vin/Id Sticker | Photo Only | - | - |
|  | Engine | Photo Only | - | - |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Rear Bumper | Broken | - | Replacement Required |
|  | Windshield | Cracked | - | > 12 Inches |
|  | Front Bumper | Broken | - | Replacement Required |
|  | Right Front Mirror Housing | Broken | - | Replacement Required |
|  | Right Front Wheel Cover | Curb Rash | - | 2 To 3 Inches |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Right Rear Wheel Cover | Curb Rash | - | > 12 Inches |
|  | Left Front Wheel Cover | Broken | - | Replacement Required |
|  | Left Rear Wheel Cover | Curb Rash | - | 4 To 5 Inches |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.