



Approved CR

IAA Fargo  
4401 37th St. N  
Branch No 363  
Fargo, ND 58102  
(701)552-9731/(701)552-9736  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 FORD  
TRANSIT-150**

Bodystyle/Series: **Wagon XL**

Color: **White**

Mileage: **97,549  
(Verified)**

Turn-in Mileage: **-**

VIN: **1FMZK1ZM3KKB28443**

Work Order/  
Stock Number: **46046173**

Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalesupport@gsa.gov**

Client Stock #: **G421215W**

Vehicle Grade : **Grade 3.0**

Remarks: **-**

Announcements: 

**• PASSENGER  
SIDE REAR  
DOOR  
DAMAGE**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

### Equipment

|                        |                               |                 |                         |
|------------------------|-------------------------------|-----------------|-------------------------|
| Transmission:          | <b>Automatic Transmission</b> | A/C:            | <b>No</b>               |
| Engine:                | <b>6-Cylinder Gas</b>         | Cruise Control: | <b>Yes</b>              |
| Engine Size:           | <b>3.7 L</b>                  | Pwr Steering:   | <b>Yes</b>              |
| Roof:                  | <b>Hard Top</b>               | Pwr Locks:      | <b>Yes</b>              |
| Radio:                 | <b>-</b>                      | Pwr Windows     | <b>Yes</b>              |
| Interior - Type/Color: | <b>Cloth Interior /BLACK</b>  | Rear Defroster: | <b>Yes</b>              |
| Airbag:                | <b>Driver Side Air Bag</b>    | Tilt Steering:  | <b>Yes</b>              |
| Seats:                 | <b>3rd</b>                    | Drive Type:     | <b>Rear Wheel Drive</b> |
| Seat Count:            | <b>-</b>                      | Brakes:         | <b>Hydraulic Brakes</b> |

## Equipment

### Additional Equipment:

Car Tire Size - LF 235 / 65 R 16

Car Tire Size - LR 235 / 65 R 16

Car Tire Size - RR 235 / 65 R 16

Car Tire Size - RF 235 / 65 R 16

LF Tires - 6/32 inch

LR Tires - 3/32 inch

RF Tires - 5/32 inch

RR Tires - 3/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE

Tire Model - LR - Transforce CV

Tire Model - RF - Transforce CV


Tire Model - RR - Transforce CV

Tire Model - LF - Transforce CV

## Non Chargeable Damages

| Photo                                                                               | Item                    | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|-------------------------|------------|--------|----------|
|    | Rear Seats              | Photo Only | -      | -        |
|    | Odometer                | Photo Only | -      | -        |
|   | Extra Photo 1           | Photo Only | -      | -        |
|  | Photo - Dash            | Photo Only | -      | -        |
|  | Right Rear Bumper/Cover | Photo Only | -      | -        |
|  | Left Rear Bumper/Cover  | Photo Only | -      | -        |
|  | Left Front Fender       | Photo Only | -      | -        |
|  | Right Front Fender      | Photo Only | -      | -        |

### Non Chargeable Damages

| Photo                                                                               | Item                   | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|------------------------|------------|--------|----------|
|    | Extra Photo 2          | Photo Only | -      | -        |
|    | Rear Bumper            | Photo Only | -      | -        |
|    | Instrument Panel       | Photo Only | -      | -        |
|    | Left Side Panel        | Photo Only | -      | -        |
|    | Right Side Panel       | Photo Only | -      | -        |
|   | Front Cover Center     | Photo Only | -      | -        |
|  | Keys                   | Photo Only | -      | -        |
|  | Engine                 | Photo Only | -      | -        |
|  | Photo - Vin/Id Sticker | Photo Only | -      | -        |

### Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|-------|------|--------|--------|----------|
|-------|------|--------|--------|----------|

### Chargeable Damages

| Photo                                                                               | Item                     | Damage                         | Action | Severity             |
|-------------------------------------------------------------------------------------|--------------------------|--------------------------------|--------|----------------------|
|    | Hood                     | Chipped                        | -      | 5                    |
|    | Front Bumper Cover Upper | Chipped                        | -      | 5                    |
|    | Right Dutch Cargo Door   | Multiple Dents/No Paint Damage | -      | 2                    |
|   | Front Ls Panel           | Heavy Scratch                  | -      | 1 To 2 Inches        |
|  | Left Rear Tire           | Worn                           | -      | Replacement Required |
|  | Right Front Wheel        | Corrosion                      | -      | 1 To 2 Inches        |

### Chargeable Damages

| Photo                                                                              | Item                  | Damage               | Action | Severity             |
|------------------------------------------------------------------------------------|-----------------------|----------------------|--------|----------------------|
|   | Left Dutch Cargo Door | Dent(S) W/ Paint Dmg | -      | > 12 Inches          |
|   | Right Rear Wheel      | Curb Rash            | -      | 1/2 To 1 Inch        |
|   | Right Rear Tire       | Worn                 | -      | Replacement Required |
|  | Left Rear Wheel       | Corrosion            | -      | 1 To 2 Inches        |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.