



Approved CR

America's Auto Auction - Pensacola, Inc
6615 Mobile Highway
Pensacola, FL 32526-1264
850-972-8601/(850) 944-8482
Della.Smith@AmericasAutoAuction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2023 FORD
TRANSIT-350
PASSENGER
VAN**

Bodystyle/Series: **3 Door
Vehicle XL
WAGON
RWD 148 WB**

Color: **WHITE**

Mileage: **127,954
(Verified, 6
digits)**

Turn-in Mileage: **-**

VIN: **1FBAX2Y88PKB58174**

Work Order/
Stock Number: **000354794**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G432987Z**

Vehicle Grade : **Grade 1.5**

Remarks: **-**

Announcements: **-**

Certification : **Not Certified**

Req. Prev. Repair
Order: **-**



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: YES

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment

Additional Equipment:

3rd Row Seat	ABS Brakes	Air Conditioning
Automatic Headlights	Auxiliary Pwr Outlet	Bluetooth Connection
Brake Assist System	Car Tire Size - LF tire size LT235/65SR16	Car Tire Size - LR tire size LT235/65SR16
Car Tire Size - RR tire size LT235/65SR16	Car Tire Size - RF tire size LT235/65SR16	Cruise Control
Cylinders - 6	Daytime Running Lights	Driver Air Bag
Empty Weight - 6023 lb	Engine Immobilizer	Heated Mirrors
Independent Climate Control	Intermittent Wipers	Keyless Entry
LF Tires - 13/32 inch	LR Tires - 8/32 inch	Lane Departure System
Master Key - 1key(s)	Motor Fuel Type - Gas	Pass. Air Bag
Power Brakes	Power Lock	Power Mirrors
Power Steering	Power Windows	Privacy Glass
RF Tires - 13/32 inch	RR Tires - 7/32 inch	Rain Sensor
Rear AC	Rear Defrost	Rear View Mirror
Reverse Camera	Seat Trim - Cloth	Side Airbags - Front
Steering Wheel Audio Control	Tilt Steering Wheel	Tilt Wheel
Tire Brand - Front Left - LF tire mfg Cooper	Tire Brand - Front Right - RF tire mfg Cooper	Tire Brand - Rear Left - LR tire mfg Hankook
Tire Brand - Rear Right - RR tire mfg Hankook	Tire Pressure Monitor System	Traction Control
Transmission - Automatic Transmission w/ Overdrive	Turn Signal Mirrors	Two-Wheel Drive
Wheels Front Left - Steel	Wheels Front Right - Steel	Wheels Rear Left - Steel
Wheels Rear Right - Steel		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown


Non Chargeable Damages


Photo	Item	Damage	Action	Severity
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	3rd Row Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Cargo Door	Multiple Scratches Light	Report	6
	Front Bumper/Cover	Multiple Scratches Light	Report	10 Or More
	Left Qtr Panel	Severe Damage	Report	Replacement Required
	Left Sunvisor	Broken	Report	Replacement Required
	Left Front Door	Multiple Scratches Light	Report	6
	Left Front Fender	Multiple Scratches Light	Report	6
	Lr Seat Belt Buckle	Broken	Report	Replacement Required

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Qtr Panel	Chipped	Report	5
	Rear Bumper/Cover	Multiple Scratches Light	Report	10 Or More
	Right Sunvisor	Broken	Report	Replacement Required
	Right Front Door	Multiple Scratches Light	Report	6
	Right Rear Seat	Torn	Report	5 To 6 Inches
	Right Rear Side Cargo Door	Multiple Scratches Light	Report	6
	3rd Row Seat	Worn	Report	Replacement Required
	Left Seat Belt 4th Row	Broken	Report	Replacement Required
[no photo]	Engine	Noise	Report	Repair Required
[no photo]	Suspension	Noise	Report	Repair Required
[no photo]	Oil	Low Fluid	Report	Unacceptable

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.