



Approved CR

America's Auto Auction - Pensacola, Inc  
6615 Mobile Highway  
Pensacola, FL 32526-1264  
850-972-8601/(850) 944-8482  
Della.Smith@AmericasAutoAuction.com  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 FORD  
TRANSIT  
CONNECT**  
**4 Door Vehicle**  
**XL**  
Bodystyle/Series: **PASSENGER  
WAGON  
WAGON**  
Color: **GRAY**  
Mileage: **85,224  
(Verified, 6  
digits)**  
Turn-in Mileage: -  
VIN: **NM0GE9E27L1437486**  
Work Order/  
Stock Number: **000354646**  
Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalesupport@gsa.gov**  
Client Stock #: **G411841W**  
Vehicle Grade : **Grade 3.1**  
Remarks: -  
Announcements: -  
Certification : **Not Certified**  
Req. Prev. Repair  
Order: -



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

#### Equipment

|                        |                               |                 |                          |
|------------------------|-------------------------------|-----------------|--------------------------|
| Transmission:          | <b>Automatic Transmission</b> | A/C:            | <b>Yes</b>               |
| Engine:                | <b>4-Cylinder Gas</b>         | Cruise Control: | <b>Yes</b>               |
| Engine Size:           | <b>2 L</b>                    | Pwr Steering:   | <b>Yes</b>               |
| Roof:                  | <b>Hard Top</b>               | Pwr Locks:      | <b>Yes</b>               |
| Radio:                 | -                             | Pwr Windows     | <b>Yes</b>               |
| Interior - Type/Color: | <b>Vinyl Interior /BLACK</b>  | Rear Defroster: | <b>Yes</b>               |
| Airbag:                | <b>Dual Air Bags</b>          | Tilt Steering:  | <b>Yes</b>               |
| Seats:                 | -                             | Drive Type:     | <b>Front Wheel Drive</b> |
| Seat Count:            | -                             | Brakes:         | <b>Power Brakes</b>      |

## Equipment


### Additional Equipment:

|                                              |                                            |                                                    |
|----------------------------------------------|--------------------------------------------|----------------------------------------------------|
| 3rd Row Seat                                 | 4th Passenger Door                         | ABS Brakes                                         |
| Air Conditioning                             | Automatic Headlights                       | Auxiliary Pwr Outlet                               |
| Bluetooth Connection                         | Brake Assist System                        | Car Tire Size - RF tire size P215/55HR16           |
| Car Tire Size - LR tire size P215/55HR16     | Car Tire Size - LF tire size P215/55HR16   | Car Tire Size - RR tire size P215/55HR16           |
| Child Safety Locks                           | Cruise Control                             | Cylinders - 4                                      |
| Daytime Running Lights                       | Driver Air Bag                             | Empty Weight - 4028 lb                             |
| Engine Immobilizer                           | Floor Mats                                 | Front Wheel Drive                                  |
| Front Wheel Drive                            | Independent Climate Control                | Intermittent Wipers                                |
| Keyless Entry                                | LF Tires - 4/32 inch                       | LR Tires - 6/32 inch                               |
| Master Key - 1key(s)                         | Motor Fuel Type - Gas                      | Pass-Through Rear Seat                             |
| Pass. Air Bag                                | Power Brakes                               | Power Lock                                         |
| Power Steering                               | Power Windows                              | Privacy Glass                                      |
| RF Tires - 4/32 inch                         | RR Tires - 8/32 inch                       | Rain Sensor                                        |
| Rear AC                                      | Rear Defrost                               | Rear Parking Aid                                   |
| Reverse Camera                               | Seat Trim - Vinyl                          | Side Airbags - Front                               |
| Tilt Steering Wheel                          | Tilt Wheel                                 | Tire Brand - Front Left - LF tire mfg Kumho        |
| Tire Brand - Front Right - RF tire mfg Kumho | Tire Brand - Rear Left - LR tire mfg Kumho | Tire Brand - Rear Right - RR tire mfg Kumho        |
| Tire Pressure Monitor System                 | Traction Control                           | Transmission - Automatic Transmission w/ Overdrive |
| Trip Computer                                | Wheels Front Left - Steel                  | Wheels Front Right - Steel                         |
| Wheels Rear Left - Steel                     | Wheels Rear Right - Steel                  |                                                    |


## Non Chargeable Damages

| Photo                                                                               | Item                   | Damage     | Action        | Severity |
|-------------------------------------------------------------------------------------|------------------------|------------|---------------|----------|
|  | Extra Photo 3          | Photo Only | Estimate Only | Unknown  |
|  | Extra Photo 5          | Photo Only | Estimate Only | Unknown  |
|  | Photo - Vin/Id Sticker | Photo Only | Estimate Only | Unknown  |

### Non Chargeable Damages

| Photo                                                                               | Item             | Damage     | Action        | Severity |
|-------------------------------------------------------------------------------------|------------------|------------|---------------|----------|
|    | Stereo           | Photo Only | Estimate Only | Unknown  |
|    | Left Rear Seat   | Photo Only | Estimate Only | Unknown  |
|    | 3rd Row Seat     | Photo Only | Estimate Only | Unknown  |
|    | Roof             | Photo Only | Estimate Only | Unknown  |
|    | Keys             | Photo Only | Estimate Only | Unknown  |
|    | Door Panels      | Photo Only | Estimate Only | Unknown  |
|  | Left Front Tire  | Photo Only | Estimate Only | Unknown  |
|  | Right Front Tire | Photo Only | Estimate Only | Unknown  |
|  | Photo - Rear     | Photo Only | Estimate Only | Unknown  |
|  | Right Rear Tire  | Photo Only | Estimate Only | Unknown  |
|  | Left Rear Tire   | Photo Only | Estimate Only | Unknown  |
|  | Extra Photo 2    | Photo Only | Estimate Only | Unknown  |
|  | Extra Photo 1    | Photo Only | Estimate Only | Unknown  |




### Non Chargeable Damages

| Photo                                                                             | Item                       | Damage     | Action        | Severity |
|-----------------------------------------------------------------------------------|----------------------------|------------|---------------|----------|
|  | Photo - Interior           | Photo Only | Estimate Only | Unknown  |
|  | Extra Photo 4              | Photo Only | Estimate Only | Unknown  |
|  | Photo - Dash               | Photo Only | Estimate Only | Unknown  |
|  | Overall Picture - Odometer | Photo Only | Estimate Only | Unknown  |
|  | Photo - Wheel              | Photo Only | Estimate Only | Unknown  |

### Chargeable Damages

| Photo                                                                               | Item              | Damage                      | Action | Severity        |
|-------------------------------------------------------------------------------------|-------------------|-----------------------------|--------|-----------------|
|   | Deck Lid          | Multiple Scratches Light    | Report | 5               |
|  | Front Bumper      | Multiple Scratches Light    | Report | 5               |
|  | Headerpanel       | Multiple Scratches Light    | Report | 5               |
|  | Hood              | Faded                       | Report | Repair Required |
|  | Left Head Lamp    | Faded                       | Report | Acceptable      |
|  | Left Qtr Panel    | Multiple Dents/Paint Damage | Remove | 4               |
|  | Left Sliding Door | Multiple Scratches Light    | Report | 3               |

### Chargeable Damages

| Photo                                                                               | Item               | Damage                         | Action | Severity   |
|-------------------------------------------------------------------------------------|--------------------|--------------------------------|--------|------------|
|    | Left Front Door    | Multiple Dents/No Paint Damage | Report | 2          |
|    | Left Front Fender  | Chipped                        | Report | 4          |
|    | Left Front Seat    | Stained                        | Report | Permanent  |
|    | Left Front Seat    | Torn                           | Report | < 1/8 Inch |
|    | Left Rear Seat     | Stained                        | Report | Permanent  |
|    | Right Head Lamp    | Faded                          | Report | Acceptable |
|   | Right Qtr Panel    | Chipped                        | Report | 4          |
|  | Rear Bumper        | Multiple Scratches Heavy       | Report | 6          |
|  | Roof               | Multiple Scratches Light       | Report | 4          |
|  | Right Front Door   | Multiple Scratches Light       | Report | 3          |
|  | Right Front Fender | Multiple Scratches Light       | Remove | 3          |
|  | Right Front Seat   | Stained                        | Report | Permanent  |
|  | Right Rear Door    | Multiple Scratches Light       | Report | 3          |

| Chargeable Damages                                                                |                  |           |        |              |
|-----------------------------------------------------------------------------------|------------------|-----------|--------|--------------|
| Photo                                                                             | Item             | Damage    | Action | Severity     |
|  | Right Rear Seat  | Stained   | Report | Permanent    |
|  | Seat Center Rear | Stained   | Report | Permanent    |
|  | 3rd Row Seat     | Stained   | Report | Permanent    |
| [no photo]                                                                        | Oil              | Low Fluid | Report | Unacceptable |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.