



Approved CR

Mid Kansas Auto Auction Wichita  
4716 S. Santa Fe  
Wichita , KS 67216  
316-500-7700/316-500-7701  
codyd@mksaa.com  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD  
TRANSIT-350**  
**Cargo Van**  
Bodystyle/Series: **T-350 148"**  
**HI RF 9500**  
**GVWR SLI**  
Color: **WHITE**  
Mileage: **24,334**  
**(Verified, 6**  
**digits)**  
Turn-in Mileage: -  
VIN: **1FTBW2XM2JKB18889**  
Work Order/  
Stock Number: **000116802**  
Customer: **GSA Fleet Vehicle Sales**  
**1800 F Street NW**  
**Washington, DC 20405**  
**fleetsalesupport@gsa.gov**  
Client Stock #: -  
Vehicle Grade : **Grade 3.0**  
AutoGrade : **3.0 - Average**  
Remarks: -  
Announcements: -  
Certification : **Not Certified**  
Req. Prev. Repair -  
Order: -



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

### Equipment

|                        |                               |                 |                         |
|------------------------|-------------------------------|-----------------|-------------------------|
| Transmission:          | <b>Automatic Transmission</b> | A/C:            | <b>Yes</b>              |
| Engine:                | <b>6-Cylinder Gas</b>         | Cruise Control: | <b>Yes</b>              |
| Engine Size:           | <b>3.7 L</b>                  | Pwr Steering:   | <b>Yes</b>              |
| Roof:                  | <b>Hard Top</b>               | Pwr Locks:      | <b>Yes</b>              |
| Radio:                 | <b>AM/FM CD</b>               | Pwr Windows     | <b>Yes</b>              |
| Interior - Type/Color: | <b>Vinyl Interior /GRAY</b>   | Rear Defroster: | <b>No</b>               |
| Airbag:                | <b>Dual Air Bags</b>          | Tilt Steering:  | <b>Yes</b>              |
| Seats:                 | -                             | Drive Type:     | <b>Rear Wheel Drive</b> |
| Seat Count:            | -                             | Brakes:         | <b>Power Brakes</b>     |

## Equipment


### Additional Equipment:

|                                                 |                                                    |                                                |
|-------------------------------------------------|----------------------------------------------------|------------------------------------------------|
| ABS Brakes                                      | Air Conditioning                                   | Auxiliary Pwr Outlet                           |
| Bluetooth Connection                            | Brake Assist System                                | CD Player                                      |
| Car Tire Size - LF tire size LT235/65SR16       | Car Tire Size - RR tire size LT235/65SR16          | Car Tire Size - RF tire size LT235/65SR16      |
| Car Tire Size - LR tire size LT235/65SR16       | Cruise Control                                     | Cylinders - 6                                  |
| Daytime Running Lights                          | Driver Air Bag                                     | Empty Weight - 5226 lb                         |
| Independent Climate Control                     | Intermittent Wipers                                | Keyless Entry                                  |
| LF Tires - 3/32 inch                            | LR Tires - 10/32 inch                              | Leather Steering Wheel                         |
| MP3 Radio                                       | Master Key - 1key(s)                               | Motor Fuel Type - Gas                          |
| Pass. Air Bag                                   | Power Brakes                                       | Power Lock                                     |
| Power Mirrors                                   | Power Steering                                     | Power Windows                                  |
| Privacy Glass                                   | RF Tires - 2/32 inch                               | RR Tires - 10/32 inch                          |
| Rear View Mirror                                | Reverse Camera                                     | Seat Trim - Vinyl                              |
| Side Airbags - Front                            | Steering Wheel Audio Control                       | Telematics                                     |
| Tilt Steering Wheel                             | Tire Brand - Front Left - LF tire mfg Hankook      | Tire Brand - Front Right - RF tire mfg Hankook |
| Tire Brand - Rear Left - LR tire mfg Pathfinder | Tire Brand - Rear Right - RR tire mfg Pathfinder   | Tire Pressure Monitor System                   |
| Traction Control                                | Transmission - Automatic Transmission w/ Overdrive | Trip Computer                                  |
| Two-Wheel Drive                                 | Wheels Front Left - Steel                          | Wheels Front Right - Steel                     |
| Wheels Rear Left - Steel                        | Wheels Rear Right - Steel                          |                                                |


## Non Chargeable Damages

| Photo                                                                               | Item                     | Damage     | Action        | Severity |
|-------------------------------------------------------------------------------------|--------------------------|------------|---------------|----------|
|  | Photo - Vin/Id Sticker   | Photo Only | Estimate Only | Unknown  |
|  | Overall Picture - Engine | Photo Only | Estimate Only | Unknown  |
|  | Extra Photo 4            | Photo Only | Estimate Only | Unknown  |
|  | Photo - Wheel            | Photo Only | Estimate Only | Unknown  |

### Non Chargeable Damages

| Photo                                                                               | Item                       | Damage     | Action        | Severity |
|-------------------------------------------------------------------------------------|----------------------------|------------|---------------|----------|
|    | Overall Picture - Odometer | Photo Only | Estimate Only | Unknown  |
|    | Extra Photo 2              | Photo Only | Estimate Only | Unknown  |
|    | Deck Lid Badge             | Photo Only | Estimate Only | Unknown  |
|    | Keys                       | Photo Only | Estimate Only | Unknown  |
|    | Roof                       | Photo Only | Estimate Only | Unknown  |
|    | Stereo                     | Photo Only | Estimate Only | Unknown  |
|  | Extra Photo 1              | Photo Only | Estimate Only | Unknown  |
|  | Photo - Interior           | Photo Only | Estimate Only | Unknown  |
|  | Photo - Dash               | Photo Only | Estimate Only | Unknown  |
|  | Extra Photo 3              | Photo Only | Estimate Only | Unknown  |
|  | Photo - Deck               | Photo Only | Estimate Only | Unknown  |

### Chargeable Damages

| Chargeable Damages                                                                  |                              |                                |              |                      |
|-------------------------------------------------------------------------------------|------------------------------|--------------------------------|--------------|----------------------|
| Photo                                                                               | Item                         | Damage                         | Action       | Severity             |
|    | Left Rocker Panel            | Multiple Scratches Heavy       | Touch Up     | 4                    |
|    | Right Rear Cargo Door        | Multiple Dents/No Paint Damage | PDR          | Pdr-6 Dents          |
|    | Left Rear Cargo Door         | Multiple Dents/No Paint Damage | PDR          | Pdr-4 Dents          |
|    | Cargo Area                   | Multiple Scratches Heavy       | Refinish     | 10 Or More           |
|    | Cargo Area                   | Multiple Dents/No Paint Damage | PDR          | Pdr-6 Dents          |
|   | Left Front Door              | Misaligned                     | Align/Adjust | Repair Required      |
|  | Left Front Pillar Wthr Strip | Torn                           | Replace      | Replacement Required |
|  | Left Front Seat              | Torn                           | Repair       | 1/2 To 1 Inch        |
|  | Left Front Tire              | Worn                           | Replace      | Replacement Required |
|  | Left Rear Door               | Dent(S) W/No Paint Dmg         | PDR          | Pdr-1 Dent           |
|  | Right Qtr Panel              | Multiple Dents/No Paint Damage | PDR          | 8                    |
|  | Right Rocker Panel           | Chipped                        | Touch Up     | 6                    |

| Chargeable Damages                                                                |                    |                                |          |                      |
|-----------------------------------------------------------------------------------|--------------------|--------------------------------|----------|----------------------|
| Photo                                                                             | Item               | Damage                         | Action   | Severity             |
|  | Right Sliding Door | Multiple Dents/No Paint Damage | PDR      | 10 Or More           |
|  | Right Front Door   | Peeling                        | Refinish | 3 To 4 Inches        |
|  | Right Front Tire   | Worn                           | Replace  | Replacement Required |
|  | Left Qtr Panel     | Multiple Dents/No Paint Damage | PDR      | Pdr-2 Dents          |
|  | Hood               | Chipped                        | Touch Up | 3                    |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.