



Approved CR

IAA Elkton
183 Zeitler Rd
Branch No 786
Elkton, MD 21921
(410) 695-4477
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 DODGE
CHARGER**
Bodystyle/Series: **- POLICE**
Color: **Black**
Mileage: **61,708
(Verified)**
Turn-in Mileage: **-**
VIN: **2C3CDXAG5JH146921**
Work Order/
Stock Number: **46434763**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G111305U**
Vehicle Grade : **Grade 3.3**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 60 R 18

Car Tire Size - LR 225 / 60 R 18

Car Tire Size - RR 225 / 60 R 18

Car Tire Size - RF 225 / 60 R 18

LF Tires - 5/32 inch

LR Tires - 7/32 inch

RF Tires - 5/32 inch

RR Tires - 7/32 inch

Tire Brand - Front Left - GOODYEAR

Tire Brand - Front Right - GOODYEAR

Tire Brand - Rear Left - GOODYEAR

Tire Brand - Rear Right - GOODYEAR

Tire Model - RR - Eagle RS-A

Tire Model - RF - Eagle RS-A

Tire Model - LR - Eagle RS-A

Tire Model - LF - Eagle RS-A

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Deck Lid	Previous Repair	-	Acceptable
	Center Console	Aftermarket	-	Acceptable
	Cargo Shelf	Aftermarket	-	Acceptable
	Aftermarket Accessory	Aftermarket	-	Acceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	3
	Right Front Door	Multiple Scratches Light	-	4
	Right Front Center Cap	Missing	-	Replacement Required
	Right Rear Door	Multiple Scratches Light	-	4
	Right Rear Center Cap	Missing	-	Replacement Required
	Rear Bumper	Chipped	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Center Cap	Missing	-	Replacement Required
	Left Drip Rail	Previous Repair	-	Substandard Repair
	Left Front Center Cap	Missing	-	Replacement Required
	Roof	Chipped	-	2
	Right Qtr Panel	Multiple Scratches Light	-	5
	Left Rear Door	Multiple Scratches Heavy	-	7

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Chipped	-	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.