Approved CR

IAA Tidewater
211 Production Drive
Branch No 725
Yorktown, VA 23693
(757) 595-8493/(757) 595-8691
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2022 FORD F-450**
Bodystyle/Series:	**Crew Cab XL**
Color:	**Black**
Mileage:	**1 (Unverified)**
Turn-in Mileage:	-
VIN:	**1FT8W4DT2NEF13645**
Work Order/ Stock Number:	**46025988**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G710102Z**
Vehicle Grade :	**Grade 0.0**
Remarks:	-
Announcements:	• SALVAGE
Certification :	-
Req. Prev. Repair Order:	-

Drivable: No

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Diesel**	Cruise Control:	**Yes**
Engine Size:	**6.7 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	-	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

Car Tire Size - RF 225 / 70 R 19.5	Car Tire Size - LR 225 / 70 R 19.5	Car Tire Size - RR 225 / 70 R 19.5
Car Tire Size - LF 225 / 70 R 19.5	LF Tires - 10/32 inch	LR Tires - 15/32 inch
RF Tires - 12/32 inch	RR Tires - 15/32 inch	Tire Brand - Front Left - CONTINENTAL
Tire Brand - Front Right - CONTINENTAL	Tire Brand - Rear Left - CONTINENTAL	Tire Brand - Rear Right - CONTINENTAL
Tire Model - LF - Conti Hybrid HD3	Tire Model - RF - Conti Hybrid HD3	Tire Model - RR - Conti Hybrid HD3
Tire Model - LR - Conti Hybrid HD3		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Frame	Corrosion	-	Severe Damage
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Dash	Burn Hole	-	> 12 Inches
	Steering Wheel	Worn	-	Replacement Required
	Rear Metal Bumper Painted	Multiple Scratches Heavy	-	3
	Rear Bumper Step Pad	Bent	-	Replacement Required
	Core Support	Broken	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Head Lamp	Missing	-	Replacement Required
	Hood	Severe Damage	-	Replacement Required
	Left Front Fender	Severe Damage	-	Replacement Required
	Grille	Missing	-	Replacement Required
	Front Bumper Cover Upper	Missing	-	Replacement Required
	Left Drip Rail	Severe Damage	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Door	Severe Damage	-	Replacement Required
	Right Head Lamp	Melted	-	Replacement Required
	Front Metal Bumper Painted	Severe Damage	-	Replacement Required
	Tailgate	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Left Rear Door	Severe Damage	-	Replacement Required
	Cab - Left	Peeling	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Engine	Broken	-	Repair Required
	Right Front Door Panel	Worn	-	Replacement Required
	Right Front Seat	Burn Hole	-	> 12 Inches
	Headlining	Burn Hole	-	> 12 Inches
	Right Rear Door Panel	Worn	-	Replacement Required
	Right Rear Seat	Burn Hole	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Seat Center Rear	Burn Hole	-	> 12 Inches
	Left Rear Seat	Burn Hole	-	> 12 Inches
	Left Front Seat	Burn Hole	-	> 12 Inches
	Center Console	Burn Hole	-	> 12 Inches
	Seat Center Front	Burn Hole	-	> 12 Inches
	Windshield	Broken	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Radio	Broken	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.