Approved CR

IAA Chicago North
605 Healy Road
Branch No 514
East Dundee, IL 60118
(847) 426-5913/(847) 541-2114
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2025 CHEVROLET EXPRESS PASSENGER**
Bodystyle/Series:	**Van RWD 2500 REGULAR**
Color:	**Silver**
Mileage:	**12,532 (Verified)**
Turn-in Mileage:	-
VIN:	**1GAWGEFPXS1136343**
Work Order/ Stock Number:	**46496244**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G43B5534**
Vehicle Grade :	**Grade 2.1**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**4.3 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth/Vinyl /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 75 R 16	Car Tire Size - RF 245 / 75 R 16	Car Tire Size - LF 245 / 75 R 16
Car Tire Size - LR 245 / 75 R 16	LF Tires - 12/32 inch	LR Tires - 12/32 inch
RF Tires - 12/32 inch	RR Tires - 11/32 inch	Tire Brand - Front Left - BRIDGESTONE
Tire Brand - Front Right - BRIDGESTONE	Tire Brand - Rear Left - BRIDGESTONE	Tire Brand - Rear Right - BRIDGESTONE
Tire Model - LF - v-Steel rib 265	Tire Model - LR - v-Steel rib 265	Tire Model - RF - v-Steel rib 265
Tire Model - RR - v-Steel rib 265		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door Panel	Multiple Scratches Light	-	3
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Chipped	-	6
	Hood	Chipped	-	2
	Right Drip Rail	Dent(S) W/ Paint Dmg	-	5 To 6 Inches
	Right Qtr Panel	Chipped	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Cargo Door	Heavy Scratch	-	1/2 To 1 Inch
	Front Ls Panel	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Drip Rail	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Rear Window	Broken	-	Replacement Required
	Left Front Door	Dent(S) W/ Paint Dmg	-	5 To 6 Inches
	Left Front Seat Cushion	Torn	-	1 To 2 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Windshield	Broken	-	Replacement Required
	5th Row Seat	Misaligned	-	Repair Required
	Roof	Severe Damage	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.