Approved
CR

Orlando Auto Auction
4636 W. Colonial Dr
Orlando, FL 32808
(407) 299-3904/(407) 294-6982
david.orlandoautoauction@gmail.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2020 DODGE DURANGO**
Bodystyle/Series:	**Sport Utility Vehicle PURSUIT**
Color:	**WHITE**
Mileage:	**119,335 (Digital)**
Turn-in Mileage:	-
VIN:	**1C4RDJFG5LC228892**
Work Order/ Stock Number:	**0318696**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G622917X**
Vehicle Grade :	**Grade 3.4**
Remarks:	-
Announcements:	• FORMER POLICE UNIT. DEFICIENCIES, WHEN KNOWN, • HAVE BEEN NOTED IN THE ITEM DESCRIPTION; HOWEVER, • THE ABSENCE OF ANY INDICATED DEFICIENCIES DOES • NOT MEAN THERE ARE NONE.
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

As Is 100K Miles: YES

Equipment

Transmission:	**Automatic Transmission w/ Overdrive**	A/C:	**Yes**

Equipment

Engine:	**6-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**- /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**Buckets**	Drive Type:	**All Wheel Drive**
Seat Count:	**0**	Brakes:	**Power Brakes**

Additional Equipment:

Automatic Headlights	Auxiliary Audio Input	Backup camera and monitor
Bluetooth Connection	Brake Assist System	Car LF Tires - 7/32 inch
Car LR Tires - 7/32 inch	Car RF Tires - 7/32 inch	Car RR Tires - 7/32 inch
Car Tire Size - LF: P265/60TR18 LR: P265/60TR18 RF: P265/60TR18 RR: P265/60TR18 SP: FULL SIZE	Child Safety Locks	Cross - Traffic Alert
Cylinders - 6	Driver Adjustable Lumbar	Driver Vanity Mirror
Electrochromic Rearview Mirror	Electronic Stability Control	Engine Immobilizer
Floor Mats	Fog Lamps	Front Head Air Bag
Heated Mirrors	Ignition Key - 2key(s)	Independent Climate Control
Intermittent Wipers	Keyless Entry - Left	Keyless Start
Knee Air Bag	LF Tires - 7/32 inch	LR Tires - 7/32 inch
Leather Steering Wheel	MP3 Radio	Misc. Special Features - Rear Collision Mitigation
Pass-Through Rear Seat	Pass. Air Bag	Passenger Air Bag Sensor
Passenger Vanity Mirror	Power Driver Seat	Power Mirrors
Privacy Glass	RF Tires - 7/32 inch	RR Tires - 7/32 inch
Rear AC	Rear Bench Seat	Rear Head Air Bag
Rear Parking Aid	Rear Spoiler	Side Airbags - Front
Smart Device Integration	Spare Tire - Full Size	Spare Wheel - Steel
Steering Wheel Audio Control	Telematics	Tilt Steering Wheel
Tire Brand - Front Left - OTHER	Tire Brand - Front Right - OTHER	Tire Brand - Rear Left - OTHER
Tire Brand - Rear Right - OTHER	Tire LF - 7/32 inch	Tire Pressure Monitor System
Tire RF - 7/32 inch	Tire Size - LF: P265/60TR18 LR: P265/60TR18 RF: P265/60TR18 RR: P265/60TR18 SP: FULL SIZE	Tire Size - LF: P265/60TR18 LR: P265/60TR18 RF: P265/60TR18 RR: P265/60TR18 SP: FULL SIZE
Tow Hitch	Transmission - Automatic Transmission	Trip Computer
Wheels Front Left - Aluminium	Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium

Equipment

Wheels Rear Right - Aluminium

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Extra Photo 8	Photo Only	-	-
	Extra Photo 9	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper/Cover	Multiple Scratches Heavy	Refinish	10 Or More
	Hood	Aftermarket	De-Identify	Removal Required
	Left Front Door	Aftermarket	De-Identify	Removal Required
	Left Front Fender	Aftermarket	De-Identify	Removal Required
	Left Front Fender	Severe Damage	Replace	Replacement Required
	Left Rear Door	Aftermarket	De-Identify	Removal Required
	Left Qtr Panel	Aftermarket	De-Identify	Removal Required
	Rear Bumper/Cover	Aftermarket	De-Identify	Removal Required
	Lift Gate	Aftermarket	De-Identify	Removal Required
	Right Front Door	Aftermarket	De-Identify	Removal Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Aftermarket	De-Identify	Removal Required
	Battery	Inoperable	Replace	Repair Required
	Left Front Seat	Worn	Replace	Replacement Required
	Warning - Traction Control	On	Mechanical Check	Unacceptable
	Warning Light - Abs	On	Mechanical Check	Unacceptable
	Warning Light - Engine	On	Mechanical Check	Unacceptable
	Right Rear Door	Aftermarket	De-Identify	Removal Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.