Approved CR

Carriage Trade Auto Auction
1200 Ridge Pike
Conshohocken, PA 19428
215-CAR-SALE/(610) 834-8274
WHOLESALE ASSESSMENT ONLY



| | |
|---|---|
| Make/Model: | **2018 FORD FUSION HYBRID S** |
| Bodystyle/Series: | **4 Door Vehicle -** |
| Color: | **BLUE** |
| Mileage: | **20,413 (Digital)** |
| Turn-in Mileage: | - |
| VIN: | **3FA6P0UU2JR278876** |
| Work Order/ Stock Number: | **0182891** |
| Customer: | GSA Fleet Vehicle Sales<br>1800 F Street NW<br>Washington, DC 20405<br>fleetsalessupport@gsa.gov |
| Client Stock #: | **G104197V** |
| Vehicle Grade : | **Grade 3.4** |
| Remarks: | - |
| Announcements: | - |
| Certification : | **Not Certified** |
| Req. Prev. Repair Order: | - |

Drivable: Yes

As Is 100K Miles: NO

## Equipment

| | | | |
|---|---|---|---|
| Transmission: | **Continuously Variable Transmission** | A/C: | **Yes** |
| Engine: | **4-Cylinder Gas** | Cruise Control: | **Yes** |
| Engine Size: | **2 L** | Pwr Steering: | **Yes** |
| Roof: | **Hard Top** | Pwr Locks: | **Yes** |
| Radio: | **CD Only** | Pwr Windows | **Yes** |
| Interior - Type/Color: | **- /GRAY** | Rear Defroster: | **Yes** |
| Airbag: | **Driver Side Air Bag** | Tilt Steering: | **No** |
| Seats: | **Buckets** | Drive Type: | **Front Wheel Drive** |
| Seat Count: | **0** | Brakes: | **Power Brakes** |

## Equipment


Additional Equipment:

| | | |
|---|---|---|
| 4th Passenger Door | Automatic Headlights | Auxiliary Pwr Outlet |
| Backup camera and monitor | Bluetooth Connection | Brake Assist System |
| Car LF Tires - 6/32 inch | Car LR Tires - 7/32 inch | Car RF Tires - 5/32 inch |
| Car RR Tires - 6/32 inch | Car Tire Size - LF: P225/50VR17 LR: P225/50VR17 RF: P225/50VR17 RR: P225/50VR17 | Child Safety Locks |
| Cylinders - 4 | Daytime Running Lights | Driver Adjustable Lumbar |
| Driver Illuminated Vanity Mirr | Driver Restriction Features | Driver Vanity Mirror |
| Electronic Stability Control | Engine Immobilizer | First Aid Kit |
| Floor Mats | Front Head Air Bag | Ignition Key - 1key(s) |
| Independent Climate Control | Intermittent Wipers | Keyless Entry - Left |
| Keyless Start | Knee Air Bag | LF Tires - 6/32 inch |
| LR Tires - 7/32 inch | MP3 Radio | Misc. Special Features - Passenger Third Door, Regenerative Brakes, Airbag Disconnect Switch |
| Pass. Air Bag | Passenger Air Bag Sensor | Passenger Illuminated Vanity M |
| Passenger Vanity Mirror | Power Mirrors | Power Trunk/Liftgate |
| Privacy Glass | RF Tires - 5/32 inch | RR Tires - 6/32 inch |
| Rear Bench Seat | Rear Head Air Bag | Remote Trunk Release |
| Security System | Side Airbags - Front | Smart Device Integration |
| Steering Wheel Audio Control | Telematics | Tilt Steering Wheel |
| Tire LF - 6/32 inch | Tire Pressure Monitor System | Tire RF - 5/32 inch |
| Tire Size - LF: P225/50VR17 LR: P225/50VR17 RF: P225/50VR17 RR: P225/50VR17 | Tire Size - LF: P225/50VR17 LR: P225/50VR17 RF: P225/50VR17 RR: P225/50VR17 | Transmission - Automatic Transmission w/ Overdrive |
| Trip Computer | Wheels Front Left - Aluminium | Wheels Front Right - Aluminium |
| Wheels Rear Left - Aluminium | Wheels Rear Right - Aluminium | |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Extra Photo 8 | Photo Only | - | - |
|  | Miscellaneous | Photo Only | - | - |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Miscellaneous | Photo Only | - | - |
|  | Miscellaneous | Photo Only | - | - |
|  | Miscellaneous | Photo Only | - | - |
|  | Miscellaneous | Photo Only | - | - |
|  | Miscellaneous | Photo Only | - | - |
|  | Extra Photo 1 | Photo Only | - | - |
|  | Extra Photo 2 | Photo Only | - | - |
|  | Extra Photo 3 | Photo Only | - | - |
|  | Extra Photo 4 | Photo Only | - | - |
|  | Extra Photo 5 | Photo Only | - | - |
|  | Extra Photo 6 | Photo Only | - | - |
|  | Extra Photo 7 | Photo Only | - | - |
|  | Extra Photo 9 | Photo Only | - | - |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
| [no photo] | Hood | Chipped | Estimate Only | 4 |
| [no photo] | Left Qtr Panel | Multiple Scratches Light | Estimate Only | 3 |
|  | Emergency Road Kit | Broken | Replace | Replacement Required |
| [no photo] | Right Rear Door | Multiple Scratches Light | Estimate Only | 2 |
|  | Oil | Low Fluid | Mechanical Check | Unacceptable |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.