Approved CR

IAA Raleigh
60 Sadisco Road
Branch No 747
Clayton, NC 27520
(919) 553-6148/(919) 553-2857
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2020 FORD FUSION**
Bodystyle/Series:	**4 Door Sedan S**
Color:	**Blue**
Mileage:	**35,131 (Verified)**
Turn-in Mileage:	-
VIN:	**3FA6P0G73LR233342**
Work Order/ Stock Number:	**46498081**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G101533X**
Vehicle Grade :	**Grade 4.5**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**2.5 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /-**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 215 / 60 R 16	Car Tire Size - LR 215 / 60 R 16	Car Tire Size - RR 215 / 60 R 16
Car Tire Size - RF 215 / 60 R 16	LF Tires - 10/32 inch	LR Tires - 11/32 inch
RF Tires - 10/32 inch	RR Tires - 11/32 inch	Tire Brand - Front Left - UNIROYAL
Tire Brand - Front Right - UNIROYAL	Tire Brand - Rear Left - UNIROYAL	Tire Brand - Rear Right - UNIROYAL
Tire Model - RR - Tiger Paw Touring A/S	Tire Model - RF - Tiger Paw Touring A/S	Tire Model - LR - Tiger Paw Touring A/S
Tire Model - LF - Tiger Paw Touring A/S		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Scuffed	-	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel Cover	Curb Rash	-	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.