Approved CR

IAA New Orleans East
6600 Almonaster Avenue
Branch No 432
New Orleans, LA 70126
(504) 240-2298/(504) 244-0883
WHOLESALE ASSESSMENT ONLY



| | |
|---|---|
| Make/Model: | **2017 FORD F-550 CHASSIS** |
| Bodystyle/Series: | **Regular Cab XL** |
| Color: | **White** |
| Mileage: | **114,227 (Verified)** |
| Turn-in Mileage: | - |
| VIN: | **1FDAF5GTXHEE87198** |
| Work Order/ Stock Number: | **46471322** |
| Customer: | GSA Fleet Vehicle Sales<br>1800 F Street NW<br>Washington, DC 20405<br>fleetsalessupport@gsa.gov |
| Client Stock #: | **G320054V** |
| Vehicle Grade : | **Grade 3.8** |
| Remarks: | - |
| Announcements: | • rear WC lift |
| Certification : | - |
| Req. Prev. Repair Order: | - |

Drivable: Yes

## Equipment

| | | | |
|---|---|---|---|
| Transmission: | **Automatic Transmission** | A/C: | **No** |
| Engine: | **8-Cylinder Diesel** | Cruise Control: | **Yes** |
| Engine Size: | **6.7 L** | Pwr Steering: | **Yes** |
| Roof: | **Hard Top** | Pwr Locks: | **No** |
| Radio: | - | Pwr Windows | **No** |
| Interior - Type/Color: | **Cloth Interior /GRAY** | Rear Defroster: | **No** |
| Airbag: | **Driver Side Air Bag** | Tilt Steering: | **Yes** |
| Seats: | **5th** | Drive Type: | **Rear Wheel Drive** |
| Seat Count: | - | Brakes: | **Anti Lock Brakes** |

## Equipment

Additional Equipment:

| | | |
|---|---|---|
| Car Tire Size - RR 225 / 70 R 19 | Car Tire Size - RF 225 / 70 R 19 | Car Tire Size - LF 225 / 70 R 19 |
| Car Tire Size - LR 225 / 70 R 19 | LF Tires - 12/32 inch | LR Tires - 10/32 inch |
| RF Tires - 10/32 inch | RR Tires - 8/32 inch | Tire Brand - Front Left - ROADMASTER |
| Tire Brand - Front Right - ROADMASTER | Tire Brand - Rear Left - GOODYEAR | Tire Brand - Rear Right - GOODYEAR |
| Tire Model - LF - RM170+ | Tire Model - LR - G647 RSS | Tire Model - RF - RM170+ |
| Tire Model - RR - G647 RSS | | |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Photo - Vin/Id Sticker | Photo Only | - | - |
|  | Engine | Photo Only | - | - |
|  | Keys | Photo Only | - | - |
|  | Front Cover Center | Photo Only | - | - |
|  | Right Side Panel | Photo Only | - | - |
|  | Left Side Panel | Photo Only | - | - |
|  | Instrument Panel | Photo Only | - | - |
|  | Rear Bumper | Photo Only | - | - |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Right Front Fender | Photo Only | - | - |
|  | Left Front Fender | Photo Only | - | - |
|  | Left Rear Bumper/Cover | Photo Only | - | - |
|  | Right Rear Bumper/Cover | Photo Only | - | - |
|  | Odometer | Photo Only | - | - |
|  | Extra Photo 1 | Photo Only | - | - |
|  | Photo - Dash | Photo Only | - | - |
|  | Rear Seats | Photo Only | - | - |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Left Front Wheel | Rust | - | Repair Required |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Right Rear Wheel | Rust | - | Repair Required |
|  | Left Rear Wheel | Rust | - | Repair Required |
|  | Right Front Wheel | Rust | - | Repair Required |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.