



Approved CR

IAA Spokane
3520 N Tschirley Rd
Branch No 322
Spokane, WA 99224
(509)891-2388/(855)631-9008
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020
CHEVROLET
SILVERADO
3500HD**

Bodystyle/Series: **- 4WD LONG
BED WT**

Color: **Blue**

Mileage: **77,593
(Verified)**

Turn-in Mileage: **-**

VIN: **1GC5YSE72LF258294**

Work Order/
Stock Number: **46387193**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G630361X**

Vehicle Grade : **Grade 3.1**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 275 / 70 R 18	Car Tire Size - LR 275 / 70 R 18	Car Tire Size - RR 275 / 70 R 18
Car Tire Size - RF 275 / 70 R 18	LF Tires - 7/32 inch	LR Tires - 9/32 inch
RF Tires - 6/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - NITTO
Tire Brand - Front Right - NITTO	Tire Brand - Rear Left - NITTO	Tire Brand - Rear Right - NITTO
Tire Model - RR - Terra Grappler	Tire Model - RF - Terra Grappler	Tire Model - LR - Terra Grappler
Tire Model - LF - Terra Grappler		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Odometer	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rf Mirror Cover	Missing	-	Replacement Required
	Overall Vehicle	Multiple Scratches Light	-	10 Or More
	Front Bumper Cover Lower	Broken	-	Replacement Required
	Right Fender Flare	Missing	-	Replacement Required
	Inside Bed	Multiple Scratches Heavy	-	10 Or More

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.