



Approved CR

IAA Metro DC  
14149 Brandywine Rd  
Brandywine, MD 20613  
(301) 372-8876/(301) 372-8285  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 DODGE  
GRAND  
CARAVAN**

Bodystyle/Series: **Van SE**

Color: **White**

Mileage: **51,611  
(Verified)**

Turn-in Mileage: **-**

VIN: **2C4RDGBG7JR248607**

Work Order/  
Stock Number: **46416987**

Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalessupport@gsa.gov**

Client Stock #: **G41-5077U**

Vehicle Grade : **Grade 3.7**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

### Equipment

|                        |                               |                 |                          |
|------------------------|-------------------------------|-----------------|--------------------------|
| Transmission:          | <b>Automatic Transmission</b> | A/C:            | <b>No</b>                |
| Engine:                | <b>6-Cylinder Flex Fuel</b>   | Cruise Control: | <b>Yes</b>               |
| Engine Size:           | <b>3.6 L</b>                  | Pwr Steering:   | <b>Yes</b>               |
| Roof:                  | <b>Hard Top</b>               | Pwr Locks:      | <b>Yes</b>               |
| Radio:                 | <b>-</b>                      | Pwr Windows     | <b>Yes</b>               |
| Interior - Type/Color: | <b>Cloth Interior /BLACK</b>  | Rear Defroster: | <b>Yes</b>               |
| Airbag:                | <b>Driver Side Air Bag</b>    | Tilt Steering:  | <b>Yes</b>               |
| Seats:                 | <b>Bench</b>                  | Drive Type:     | <b>Front Wheel Drive</b> |
| Seat Count:            | <b>-</b>                      | Brakes:         | <b>Anti Lock Brakes</b>  |

## Equipment

### Additional Equipment:

|                                         |                                         |                                         |
|-----------------------------------------|-----------------------------------------|-----------------------------------------|
| Car Tire Size - LF 225 / 65 R 17        | Car Tire Size - LR 225 / 65 R 17        | Car Tire Size - RR 225 / 65 R 17        |
| Car Tire Size - RF 225 / 65 R 17        | LF Tires - 7/32 inch                    | LR Tires - 7/32 inch                    |
| RF Tires - 7/32 inch                    | RR Tires - 7/32 inch                    | Tire Brand - Front Left - UNIROYAL      |
| Tire Brand - Front Right - UNIROYAL     | Tire Brand - Rear Left - UNIROYAL       | Tire Brand - Rear Right - UNIROYAL      |
| Tire Model - RR - Tiger Paw Touring A/S | Tire Model - RF - Tiger Paw Touring A/S | Tire Model - LR - Tiger Paw Touring A/S |
| Tire Model - LF - Tiger Paw Touring A/S |                                         |                                         |

## Non Chargeable Damages

| Photo                                                                               | Item                    | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|-------------------------|------------|--------|----------|
|    | Left Front Fender       | Photo Only | -      | -        |
|    | Right Side Panel        | Photo Only | -      | -        |
|   | Right Rear Bumper/Cover | Photo Only | -      | -        |
|  | Photo - Dash            | Photo Only | -      | -        |
|  | Extra Photo 1           | Photo Only | -      | -        |
|  | Odometer                | Photo Only | -      | -        |
|  | Rear Seats              | Photo Only | -      | -        |
|  | Left Side Panel         | Photo Only | -      | -        |

### Non Chargeable Damages

| Photo                                                                               | Item                   | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|------------------------|------------|--------|----------|
|    | Instrument Panel       | Photo Only | -      | -        |
|    | Rear Bumper            | Photo Only | -      | -        |
|    | Extra Photo 2          | Photo Only | -      | -        |
|    | Extra Photo 3          | Photo Only | -      | -        |
|    | Right Front Fender     | Photo Only | -      | -        |
|   | Extra Photo 4          | Photo Only | -      | -        |
|  | Extra Photo 5          | Photo Only | -      | -        |
|  | Extra Photo 6          | Photo Only | -      | -        |
|  | Photo - Vin/Id Sticker | Photo Only | -      | -        |
|  | Engine                 | Photo Only | -      | -        |
|  | Keys                   | Photo Only | -      | -        |

### Non Chargeable Damages

| Photo                                                                             | Item                   | Damage     | Action | Severity |
|-----------------------------------------------------------------------------------|------------------------|------------|--------|----------|
|  | Front Cover Center     | Photo Only | -      | -        |
|  | Left Rear Bumper/Cover | Photo Only | -      | -        |

### Chargeable Damages

| Photo                                                                               | Item            | Damage   | Action | Severity      |
|-------------------------------------------------------------------------------------|-----------------|----------|--------|---------------|
|    | Left Qtr Panel  | Chipped  | -      | 2             |
|   | Left Rear Door  | Chipped  | -      | 3             |
|  | Front Bumper    | Chipped  | -      | 10 Or More    |
|  | Hood            | Oxidized | -      | 1/2 To 1 Inch |
|  | Right Rear Door | Chipped  | -      | 1             |

| Chargeable Damages                                                                  |                   |               |        |                 |
|-------------------------------------------------------------------------------------|-------------------|---------------|--------|-----------------|
| Photo                                                                               | Item              | Damage        | Action | Severity        |
|    | Lift Gate         | Chipped       | -      | 1               |
|    | Right Head Lamp   | Faded         | -      | Repair Required |
|    | Left Head Lamp    | Faded         | -      | Repair Required |
|   | Rear Bumper       | Heavy Scratch | -      | 3 To 4 Inches   |
|  | Left Front Fender | Heavy Scratch | -      | 1/2 To 1 Inch   |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.