



Approved CR

IAA Indianapolis
3302 South Harding Street
Branch No 541
Indianapolis, IN 46217
(317) 787-3202/(317)783-0586
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD
FUSION
HYBRID**

Bodystyle/Series: **4 Door Sedan
S**

Color: **Gold**

Mileage: **48,788
(Verified)**

Turn-in Mileage: **-**

VIN: **3FA6P0UU6JR101165**

Work Order/
Stock Number: **46416819**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G101344U**

Vehicle Grade : **Grade 4.0**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	Yes
Roof:	Vinyl Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /-	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 225 / 50 R 17	Car Tire Size - RF 225 / 50 R 17	Car Tire Size - LF 225 / 50 R 17
Car Tire Size - LR 225 / 50 R 17	LF Tires - 4/32 inch	LR Tires - 4/32 inch
RF Tires - 3/32 inch	RR Tires - 4/32 inch	Tire Brand - Front Left - MICHELIN
Tire Brand - Front Right - MICHELIN	Tire Brand - Rear Left - MICHELIN	Tire Brand - Rear Right - MICHELIN
Tire Model - LF - Energy Saver A/S	Tire Model - LR - Energy Saver A/S	Tire Model - RF - Energy Saver A/S
Tire Model - RR - Energy Saver A/S		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	7

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Tire	Worn	-	Replacement Required
	Left Rear Wheel	Curb Rash	-	1 To 2 Inches
	Rear Bumper	Chipped	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.