Approved CR

IAA Tidewater
211 Production Drive
Branch No 725
Yorktown, VA 23693
(757) 595-8493/(757) 595-8691
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2022 DODGE DURANGO**
Bodystyle/Series:	**Sport Utility Vehicle PURSUIT AWD**
Color:	**White**
Mileage:	**69,441 (Verified)**
Turn-in Mileage:	-
VIN:	**1C4RDJFG9NC132573**
Work Order/ Stock Number:	**46379282**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G623291Y**
Vehicle Grade :	**Grade 3.5**
Remarks:	-
Announcements:	• Prior Law Enforcement
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**3rd**	Drive Type:	**All Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

Car Tire Size - LF 255 / 60 R 18	Car Tire Size - LR 255 / 60 R 18	Car Tire Size - RR 255 / 60 R 18
Car Tire Size - RF 255 / 60 R 18	LF Tires - 9/32 inch	LR Tires - 7/32 inch
RF Tires - 7/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - FIRESTONE
Tire Brand - Front Right - FIRESTONE	Tire Brand - Rear Left - FIRESTONE	Tire Brand - Rear Right - FIRESTONE
Tire Model - RR - Firehawk GT Pursuit	Tire Model - RF - Firehawk GT Pursuit	Tire Model - LR - Firehawk GT Pursuit
Tire Model - LF - Firehawk GT Pursuit		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Left Drip Rail	Previous Repair	-	Acceptable
	Led Flashlight	Aftermarket	-	Acceptable
	Roof	Previous Repair	-	Acceptable
	Center Console	Aftermarket	-	Acceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Door Panel	Aftermarket	-	Acceptable
	Left Rear Door Panel	Aftermarket	-	Acceptable
	Aftermarket Accessory	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	2
	Right Front Door	Chipped	-	8
	Rear Bumper	Chipped	-	8
	Left Front Door	Multiple Scratches Heavy	-	3
	Left Front Fender	Multiple Scratches Light	-	3
	Left Front Seat Molding	Misaligned	-	Repair Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Steering Wheel	Worn	-	Replacement Required
	Overall Vehicle	De-Identify	-	Removal Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.