



Approved
CR

IAA Fargo
4401 37th St. N
Branch No 363
Fargo, ND 58102
(701)552-9731/(701)552-9736
WHOLESALE ASSESSMENT ONLY

Make/Model: **2021 NISSAN
ALTIMA**

Bodystyle/Series: **4 Door Sedan SV
INTELLIGENT
AWD**

Color: **Black**

Mileage: **115,706
(Verified)**

Turn-in Mileage: **-**

VIN: **1N4BL4DW2MN414059**

Work Order/
Stock Number: **46295191**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G100801Y**

Vehicle Grade : **Grade 3.4**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	All Wheel Drive
Seat Count:	-	Brakes:	Hydraulic Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 215 / 55 R 17

Car Tire Size - RF 215 / 55 R 17

Car Tire Size - LF 215 / 55 R 17

Car Tire Size - LR 215 / 55 R 17

LF Tires - 4/32 inch

LR Tires - 2/32 inch

RF Tires - 4/32 inch

RR Tires - 1/32 inch

Tire Brand - Front Left - SUMITOMO

Tire Brand - Front Right - SUMITOMO

Tire Brand - Rear Left - SUMITOMO

Tire Brand - Rear Right - SUMITOMO

Tire Model - LF - HTR A/S P03

Tire Model - LR - HTR A/S P03

Tire Model - RF - HTR A/S P03

Tire Model - RR - HTR A/S P03

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Hood	Chipped	-	3
	Right Rear Wheel	Curb Rash	-	2 To 3 Inches
	Right Rear Tire	Worn	-	Replacement Required
	Rear Bumper	Multiple Scratches Heavy	-	6
	Left Rear Wheel	Curb Rash	-	1/2 To 1 Inch
	Left Rear Tire	Worn	-	Replacement Required

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Qtr Panel	Heavy Scratch	-	3 To 4 Inches
	Front Bumper	Bug Damage	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.