Approved CR

IAA Seattle
15801 110th Ave E
Branch No 327
Puyallup, WA 98374
(253)604-2300/(253)604-2390
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2023 FORD POLICE INTERCEPTOR**
Bodystyle/Series:	**Sport Utility Vehicle -**
Color:	**White**
Mileage:	**91,434 (Verified)**
Turn-in Mileage:	-
VIN:	**1FM5K8AB2PGB38442**
Work Order/ Stock Number:	**46338035**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G62A5145**
Vehicle Grade :	**Grade 4.1**
Remarks:	-
Announcements:	• CONDITION UNKNOWN • SALVAGE STAMPED CERTIFICATE TO OBTAIN TITLE WILL BE ISSUED • REAR DOORS / WINDOWS INOPERABLE MAY BE INOPERABLE • FORMER POLICE VEHICLE
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**

Equipment

Engine:	**6-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**3.3 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**4th**	Drive Type:	**All Wheel Drive**
Seat Count:	-	Brakes:	**Disc**


Additional Equipment:

Car Tire Size - LF 255 / 60 R 18	Car Tire Size - RR 255 / 60 R 18	Car Tire Size - LR 255 / 60 R 18
Car Tire Size - RF 255 / 60 R 18	LF Tires - 7/32 inch	LR Tires - 8/32 inch
RF Tires - 5/32 inch	RR Tires - 5/32 inch	Tire Brand - Front Left - TOYO
Tire Brand - Front Right - TOYO	Tire Brand - Rear Left - TOYO	Tire Brand - Rear Right - TOYO
Tire Model - LF - Open Country Q/T	Tire Model - LR - Open Country Q/T	Tire Model - RF - Open Country Q/T
Tire Model - RR - Open Country Q/T		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Aftermarket Accessory	Aftermarket	-	Acceptable
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Left A Pillar	Hole(S)	-	Alteration

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Overall Vehicle	De-Identify	-	Removal Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.