



Approved
CR

IAA Buffalo
366 Vulcan Street
Branch No 624
Buffalo, NY 14204
(716) 874-9890/(716) 874-9605
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 RAM 2500**
Bodystyle/Series: **- TRADESMAN 4X4
8' BOX**
Color: **Blue**
Mileage: **55,930 (Verified)**
Turn-in Mileage: **-**
VIN: **3C6MR5AL8HG724708**
Work Order/
Stock Number: **46378839**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G631908U**
Vehicle Grade : **Grade 3.2**
Remarks: **-**
Announcements: **• ANNOUNCEMENTS:**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Carriage	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RF 245 / 70 R 1

Car Tire Size - RR 245 / 70 R 1

Car Tire Size - LF 245 / 70 R 1

Car Tire Size - LR 245 / 70 R 1

LF Tires - 7/32 inch

LR Tires - 7/32 inch

RF Tires - 7/32 inch

RR Tires - 7/32 inch

Tire Brand - Front Left - GOODYEAR

Tire Brand - Front Right - GOODYEAR

Tire Brand - Rear Left - GOODYEAR

Tire Brand - Rear Right - GOODYEAR

Tire Model - RR - Wrangler HT

Tire Model - RF - Wrangler HT

Tire Model - LR - Wrangler HT

Tire Model - LF - Wrangler HT

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tonneau Cover	Aftermarket	-	Acceptable
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Rear Wheel	Curb Rash	-	1/2 To 1 Inch
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Hood Insulation	Torn	-	> 12 Inches
	Left Front Fender	Chipped	-	3
	Hood	Multiple Dents/Paint Damage	-	2
	Right Bed Side	Multiple Scratches Heavy	-	3

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Wheel	Corrosion	-	5 To 6 Inches
	Right Front Fender	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Tailgate	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Left Rear Wheel	Corrosion	-	2 To 3 Inches
	Left Front Door	Chipped	-	2
	Left Front Wheel	Corrosion	-	5 To 6 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.