



Approved CR

IAA Honolulu
91-445A Komohana St
Branch No 114
Kapolei, HI 96707
(808) 682-2858/(808) 682-3988
WHOLESALE ASSESSMENT ONLY

Make/Model: **2012 FORD
SUPER
DUTY F-550
DRW**

Bodystyle/Series: **Regular Cab
XL**

Color: **Gray**

Mileage: **67,080
(Verified)**

Turn-in Mileage: **-**

VIN: **1FDUF5GT0CEC39323**

Work Order/
Stock Number: **46206275**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G710036Y**

Vehicle Grade : **Grade 3.1**

Remarks: **-**

Announcements:

**• WARNING
INDICATOR
LIGHT ON
(SEE IAA
CONDITION
REPORT
FOR
DETAILS) R**

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Diesel	Cruise Control:	No
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	Vinyl Interior /GRAY	Rear Defroster:	No

Equipment

Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Memory	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Hydraulic Brakes
Additional Equipment:			
Car Tire Size - RR 225 / 70 R 19.5	Car Tire Size - RF 225 / 70 R 19.5	Car Tire Size - LF 225 / 70 R 19.5	
Car Tire Size - LR 225 / 70 R 19.5	LF Tires - 12/32 inch	LR Tires - 13/32 inch	
RF Tires - 11/32 inch	RR Tires - 4/32 inch	Tire Brand - Front Left - NAVITRAC	
Tire Brand - Front Right - NAVITRAC	Tire Brand - Rear Left - NAVITRAC	Tire Brand - Rear Right - NAVITRAC	
Tire Model - LF - N346	Tire Model - LR - N575	Tire Model - RF - N346	
Tire Model - RR - N575			

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Warning Light - Wrench	On	-	Unacceptable
	Warning Light - Engine	On	-	Unacceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Pickup Bed	Aftermarket	-	Acceptable
	Frame	Rust	-	Naaa Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Rust	-	Repair Required
	Right Rear Wheel	Rust	-	Repair Required
	Cargo Area	Rust	-	> 12 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Rust	-	Repair Required
	Left Front Wheel	Rust	-	Repair Required
	Roof Panel	Chipped	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.