Approved CR

Dealers Auto Auction of Mobile
3030 McVay Drive North
Mobile, AL 36606
2513387653
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2019 RAM 1500 CLASSIC**
Bodystyle/Series:	**Crew Cab TRADESMAN CREW CAB 2WD SWB**
Color:	**GRAY**
Mileage:	**71,654 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**1C6RR6KGXKS666551**
Work Order/ Stock Number:	**000593426**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**422202W**
Vehicle Grade :	**Grade 3.4**
AutoGrade :	**3.4 - Average**
Remarks:	-
Announcements:	-
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**6-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**Vinyl Interior /GRAY**	Rear Defroster:	**No**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	-	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

ABS Brakes	Air Conditioning	Automatic Headlights
Bedliner	Bluetooth Connection	Brake Assist System
Car Tire Size - Hood	Car Tire Size - RF tire size P265/70SR17	Car Tire Size - RR tire size P265/70SR17
Car Tire Size - LR tire size P265/70SR17	Car Tire Size - LF tire size P265/70SR17	Child Safety Locks
Cruise Control	Cylinders - 6	Daytime Running Lights
Driver Air Bag	Electrochromic Rearview Mirror	Engine Immobilizer
Heated Mirrors	Intermittent Wipers	Keyless Entry
LF Tires - 9/32 inch	LR Tires - 9/32 inch	MP3 Radio
Master Key - 2key(s)	Motor Fuel Type - Other	Pass. Air Bag
Power Brakes	Power Lock	Power Mirrors
Power Steering	Power Windows	Privacy Glass
RF Tires - 9/32 inch	RR Tires - 9/32 inch	Rear View Mirror
Reverse Camera	Seat Trim - Vinyl	Side Airbags - Front
Spare Tire	Stereo - AM/FM Radio	Tilt Steering Wheel
Tilt Wheel	Tire Brand - Front Left - L qtr panel	Tire Brand - Front Left - LF tire mfg Goodyear
Tire Brand - Front Right - RF tire mfg Goodyear	Tire Brand - Rear Left - LR tire mfg Goodyear	Tire Brand - Rear Right - RR tire mfg Goodyear
Tire Pressure Monitor System	Traction Control	Transmission - Automatic Transmission
Two-Wheel Drive	Wheels Front Left - Steel	Wheels Front Right - Steel
Wheels Rear Left - Steel	Wheels Rear Right - Steel	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Stereo	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Trunk	Photo Only	Estimate Only	Unknown
	Left Front Fender	Photo Only	Estimate Only	Unknown
	Right Front Fender	Photo Only	Estimate Only	Unknown
	Right Qtr Panel	Photo Only	Estimate Only	Unknown
	Left Qtr Panel	Photo Only	Estimate Only	Unknown
	Hood	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Photo - Front	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Chipped	Repair	5
	Right Rear Door	Chipped	Repair	9
	Front Bumper	Multiple Scratches Heavy	Repair	8
	Left Bed Side	Multiple Scratches Heavy	Repair	6
	Left Front Fender	Multiple Scratches Heavy	Repair	6
	Right Front Door	Chipped	Repair	8
[no photo]	Hood	Multiple Scratches Heavy	Repair	8
[no photo]	Left Front Door	Multiple Scratches Heavy	Repair	7
[no photo]	Left Rear Door	Multiple Scratches Heavy	Repair	8

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.