Approved CR

IAA Austin North
23010 Firefly Rd
Branch No 457
Florence, TX 76527
2549700575
mgr-austinnorth@iaai.com
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2018 FORD TRANSIT-350**
Bodystyle/Series:	**Wagon XL**
Color:	**Black**
Mileage:	**60,604 (Verified)**
Turn-in Mileage:	-
VIN:	**1FBZX2ZM7JKB31294**
Work Order/ Stock Number:	**46103247**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	-
Vehicle Grade :	**Grade 2.8**
Remarks:	-
Announcements:	• Hail Damage
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**3.7 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**4th**	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 235 / 65 R 16	Car Tire Size - LR 235 / 65 R 16	Car Tire Size - RR 235 / 65 R 16
Car Tire Size - RF 235 / 65 R 16	LF Tires - 4/32 inch	LR Tires - 4/32 inch
RF Tires - 4/32 inch	RR Tires - 4/32 inch	Tire Brand - Front Left - TOYO
Tire Brand - Front Right - TOYO	Tire Brand - Rear Left - TOYO	Tire Brand - Rear Right - TOYO
Tire Model - RR - H08+	Tire Model - RF - H08+	Tire Model - LR - H08+
Tire Model - LF - H08+		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Warning - Tire Pressure	On	-	Unacceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Headlining	Loose	-	Repair Required
	3rd Row Seat	Torn	-	4 To 5 Inches
	Right Rear Seat Cushion	Torn	-	3 To 4 Inches
	Cargo Box Left Side Wall	Multiple Scratches Heavy	-	2
	Left Rear Cargo Door	Dent(S) W/No Paint Dmg	-	3 To 4 Inches
	Hood	Hail Damage	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof Panel	Hail Damage	-	9

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.