



Approved CR

IAA Louisville North
891 Ballardsville Road
Branch No 669
Eminence, KY 40019
(502) 215-4804
WHOLESALE ASSESSMENT ONLY

Make/Model: **2021
HYUNDAI
ELANTRA**

Bodystyle/Series: **4 Door Sedan
SE**

Color: **White**

Mileage: **67,483
(Verified)**

Turn-in Mileage: **-**

VIN: **5NPLL4AG2MH048521**

Work Order/
Stock Number: **46175609**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G134096Y**

Vehicle Grade : **Grade 3.6**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 195 / 65 R 15

Car Tire Size - RF 195 / 65 R 15

Car Tire Size - LF 195 / 65 R 15

Car Tire Size - LR 195 / 65 R 15

LF Tires - 5/32 inch

LR Tires - 6/32 inch

RF Tires - 6/32 inch

RR Tires - 5/32 inch

Tire Brand - Front Left - HANKOOK

Tire Brand - Front Right - HANKOOK

Tire Brand - Rear Left - HANKOOK

Tire Brand - Rear Right - HANKOOK

Tire Model - LF - Kinergy GT H436

Tire Model - LR - Kinergy GT H436

Tire Model - RF - Kinergy GT H436

Tire Model - RR - Kinergy GT H436

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Warning Light - Engine	On	-	Unacceptable
	Engine	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Chipped	-	4
	Left Front Fender Liner	Missing	-	Replacement Required
	Right Front Fender Liner	Missing	-	Replacement Required

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper	Misaligned	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.