



Original CR

IAA Providence
160 Amaral St
Branch No 644
Riverside, RI 02915
(401) 438-5254/(401) 438-3523
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016
CHEVROLET
EXPRESS
3500**

Bodystyle/Series: **- LT**

Color: **Silver**

Mileage: **66,439
(Verified)**

Turn-in Mileage: **-**

VIN: **1GAZGPF6G1210686**

Work Order/
Stock Number: **46455964**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G43A3441**

Vehicle Grade : **Photo Only**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	4.8 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	4th	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 75 R 16

Car Tire Size - RF 245 / 75 R 16

Car Tire Size - LF 245 / 75 R 16

Car Tire Size - LR 245 / 75 R 16

LF Tires - 7/32 inch

LR Tires - 4/32 inch

RF Tires - 6/32 inch

RR Tires - 4/32 inch

Tire Brand - Front Left - LINGLONG

Tire Brand - Front Right - CROSSWIND

Tire Brand - Rear Left - CROSSWIND

Tire Brand - Rear Right - CROSSWIND

Tire Model - LF - Crosswind L/T

Tire Model - LR - Crosswind L/T

Tire Model - RF - Crosswind L/T

Tire Model - RR - Crosswind L/T

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.