



Approved
CR

IAA Syracuse
8459 Brewerton Road
Branch No 628
Cicero, NY 13039
(315) 699-2622/(315) 699-5481
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 FORD F-250**
Bodystyle/Series: **Crew Cab XL**
Color: **Blue**
Mileage: **74,598 (Verified)**
Turn-in Mileage: **-**
VIN: **1FT7W2B64KEF04213**
Work Order/
Stock Number: **46356788**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G631942W**
Vehicle Grade : **Grade 3.7**
Remarks: **-**
Announcements:

**• ANNOUNCEMENTS:
Rust/ Corrosion**

Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 285 / 70 R 17

Car Tire Size - LR 285 / 70 R 17

Car Tire Size - RR 285 / 70 R 17

Car Tire Size - RF 285 / 70 R 17

LF Tires - 14/32 inch

LR Tires - 10/32 inch

RF Tires - 14/32 inch

RR Tires - 11/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE


Tire Model - RR - Destination M/T2

Tire Model - RF - Destination M/T2

Tire Model - LR - Destination M/T2

Tire Model - LF - Destination M/T2

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Running Board	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Tailgate	Multiple Scratches Light	-	4
	Left Running Board	Aftermarket	-	Acceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Chipped	-	3
	Front Valance	Cracked	-	2 To 3 Inches
	Right Front Fender	Chipped	-	2

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Wheel	Corrosion	-	5 To 6 Inches
	Right Rear Wheel	Corrosion	-	2 To 3 Inches
	Left Front Wheel	Corrosion	-	3 To 4 Inches
	Left Front Seat Cushion	Torn	-	5 To 6 Inches
	Tailgate	Dent(S) W/No Paint Dmg	-	1/2 To 1 Inch
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	1 To 2 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Corrosion	-	4 To 5 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.