



Approved CR

IAA Dothan
15994 Us Highway 431 N
Branch No 731
Headland, AL 36345
(334) 693-4910/(334) 693-4920
WHOLESALE ASSESSMENT ONLY

Make/Model: **2023
CHRYSLER
PACIFICA
HYBRID**

Bodystyle/Series: **Van
TOURING L**

Color: **White**

Mileage: **112,048
(Verified)**

Turn-in Mileage: **-**

VIN: **2C4RC1L7XPR569449**

Work Order/
Stock Number: **46368497**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**

Client Stock #: **G41A3585**

Vehicle Grade : **Grade 3.8**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment


Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	6-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 235 / 65 R 17	Car Tire Size - RF 235 / 65 R 17	Car Tire Size - LF 235 / 65 R 17
Car Tire Size - LR 235 / 65 R 17	LF Tires - 8/32 inch	LR Tires - 10/32 inch
RF Tires - 8/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - FIRESTONE
Tire Brand - Front Right - FIRESTONE	Tire Brand - Rear Left - FIRESTONE	Tire Brand - Rear Right - SUREDRIVE
Tire Model - LF - Destination LE3	Tire Model - LR - Destination LE3	Tire Model - RF - Destination LE3
Tire Model - RR - Touring A/S		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Bumper	Multiple Scratches Heavy	-	4
	Right Front Fender	Chipped	-	1
	Right Front Door	Heavy Scratch	-	1 To 2 Inches
	Rf Mirror Cover	Heavy Scratch	-	3 To 4 Inches
	Front Bumper	Chipped	-	2

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Hood	Chipped	-	10 Or More
	Left Qtr Panel	Dent(S) W/ Paint Dmg	-	1/8 To 1/2 Inch
	Front Bumper	Dent(S) W/ Paint Dmg	-	1/8 To 1/2 Inch
	Right Rear Wheel	Curb Rash	-	2 To 3 Inches
	Right Rocker Panel Molding	Heavy Scratch	-	3 To 4 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.