



Approved CR

Dealers Auto Auction of Little Rock
4600 S University Ave
Little Rock , AR 72204
501-904-9988
WHOLESALE ASSESSMENT ONLY

Make/Model: 2017
CHEVROLET
SILVERADO
2500HD
4 Door
Vehicle
Bodystyle/Series: WORK
TRUCK
DOUBLE
CAB 4WD
SWB
Color: WHITE
Mileage: 45,767
(Verified, 6
digits)
Turn-in Mileage: -
VIN: 1GC2KUEG0HZ330454
Work Order/
Stock Number: 000072295
Customer: GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov
Client Stock #: G631424U
Vehicle Grade : Grade 2.6
Remarks: -
Announcements: • Hail Damage
Certification : Not Certified
Req. Prev. Repair -
Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Vinyl Interior /BLACK	Rear Defroster:	No
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	4-Wheel Drive

Equipment

Seat Count: -	Brakes:	Power Brakes
Additional Equipment:		
4 Wheel Drive	4 Wheel Drive	ABS Brakes
Air Conditioning	Bluetooth Connection	Car Tire Size - RR tire size LT245/75R17E
Car Tire Size - RF tire size LT245/75R17E	Car Tire Size - LF tire size LT245/75R17E	Car Tire Size - LR tire size LT245/75R17E
Cruise Control	Cylinders - 8	Daytime Running Lights
Driver Air Bag	LF Tires - 5/32 inch	LR Tires - 5/32 inch
MP3 Radio	Master Key - 2key(s)	Motor Fuel Type - Other
Pass. Air Bag	Power Brakes	Power Lock
Power Steering	Power Windows	RF Tires - 6/32 inch
RR Tires - 5/32 inch	Reverse Camera	Seat Trim - Vinyl
Side Airbags - Front	Spare Tire	Stereo - AM/FM Radio
Telematics	Tilt Steering Wheel	Tilt Wheel
Tire Brand - Front Left - LF tire mfg Firestone	Tire Brand - Front Left - Hood	Tire Brand - Front Right - RF tire mfg Firestone
Tire Brand - Rear Left - LR tire mfg Firestone	Tire Brand - Rear Right - RR tire mfg Firestone	Tire Pressure Monitor System
Tow Hitch	Traction Control	Transmission - Automatic Transmission
Wheels Front Left - Steel	Wheels Front Right - Steel	Wheels Rear Left - Steel
Wheels Rear Right - Steel		


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Photo - Front	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Right Qtr Panel	Photo Only	Estimate Only	Unknown
	Left Qtr Panel	Photo Only	Estimate Only	Unknown
	Hood	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Hail Damage	Repair	10 Or More
	Right Front Door	Multiple Dents/No Paint Damage	Repair	4
	Tailgate	Dent(S) W/No Paint Dmg	Repair	3 To 4 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Hood	Hail Damage	Repair	10 Or More
	Inside Bed	Multiple Dents/Paint Damage	Repair	10 Or More
	Left Bed Side	Multiple Dents/Paint Damage	Repair	3
	Left Front Seat Cushion	Torn	Repair	2 To 3 Inches
	Right Bed Side	Multiple Dents/No Paint Damage	Repair	4

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.