



Approved CR

IAA Fresno
1805 N Lafayette Ave
Branch No 337
Fresno, CA 93705
(559) 264-5033 / (559) 264-4251
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 RAM
PROMASTER
2500**

Bodystyle/Series: **Cargo Van
WINDOW
VAN HIGH
ROOF 15**

Color: **White**

Mileage: **100,859
(Verified)**

Turn-in Mileage: **-**

VIN: **3C6TRVPG6KE543647**

Work Order/
Stock Number: **46374695**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G310095W**

Vehicle Grade : **Grade 3.2**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	No
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	4th	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 75 R 16	Car Tire Size - LR 225 / 75 R 16	Car Tire Size - RR 225 / 75 R 16
Car Tire Size - RF 225 / 75 R 16	LF Tires - 10/32 inch	LR Tires - 10/32 inch
RF Tires - 10/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - VREDESTEIN
Tire Brand - Front Right - VREDESTEIN	Tire Brand - Rear Left - VREDESTEIN	Tire Brand - Rear Right - VREDESTEIN
Tire Model - RR - Pinza HT	Tire Model - RF - Pinza HT	Tire Model - LR - Pinza HT
Tire Model - LF - Pinza HT		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Overall Vehicle	De-Identify	-	Removal Required
	Right Front Door	Peeling	-	> 12 Inches
	Left Front Door	Peeling	-	1 To 2 Inches
	Front Ls Panel	Heavy Scratch	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.