Approved CR

Rawls Auto Auction Inc.
2818 Pond Branch Rd.
Leesville, SC 29070
(803) 859-5111/(803) 859-0517
wendyc@rawlsautoauction.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2016 FORD FUSION HYBRID**
Bodystyle/Series:	**4 Door Vehicle S 4D SEDAN**
Color:	**WHITE**
Mileage:	**38,455 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**3FA6P0UU8GR188169**
Work Order/ Stock Number:	**000381818**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G10A0184**
Vehicle Grade :	**Grade 3.9**
Remarks:	-
Announcements:	-
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**4-Cylinder Hybrid**	Cruise Control:	**Yes**
Engine Size:	**2 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM CD**	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	-	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Equipment


Additional Equipment:

4th Passenger Door	ABS Brakes	Air Conditioning
Automatic Headlights	Auxiliary Pwr Outlet	Bluetooth Connection
Brake Assist System	CD Player	Car Tire Size - RR tire size P225/50HR17
Car Tire Size - RF tire size P225/50HR17	Car Tire Size - LR tire size P225/50HR17	Car Tire Size - LF tire size P225/50HR17
Child Safety Locks	Cruise Control	Cylinders - 4
Daytime Running Lights	Driver Air Bag	Dual Air Conditioning
Empty Weight - 3615 lb	Engine Immobilizer	First Aid Kit
Floor Mats	Front Wheel Drive	Front Wheel Drive
Independent Climate Control	Intermittent Wipers	Keyless Entry
LF Tires - 8/32 inch	LR Tires - 8/32 inch	MP3 Radio
Master Key - 2key(s)	Motor Fuel Type - Other	OK Odor
Owner's Manual	Pass. Air Bag	Power Brakes
Power Lock	Power Mirrors	Power Steering
Power Trunk/Liftgate	Power Windows	Privacy Glass
RF Tires - 8/32 inch	RR Tires - 8/32 inch	Rear Defrost
Remote Trunk Release	Reverse Camera	Seat Trim - Cloth
Security System	Side Airbags - Front	Steering Wheel Audio Control
Stereo - AM/FM Radio	Telematics	Tilt Steering Wheel
Tire Brand - Front Left - LF tire mfg Laufenn	Tire Brand - Front Right - RF tire mfg Laufenn	Tire Brand - Rear Left - LR tire mfg Laufenn
Tire Brand - Rear Right - RR tire mfg Laufenn	Tire Pressure Monitor System	Traction Control
Transmission - Automatic Transmission w/ Overdrive	Trip Computer	Warranty Books
Wheels Front Left - Aluminium	Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium
Wheels Rear Right - Aluminium		


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
[no photo]	Front Bumper/Cover	Chipped	Touch Up	10 Or More
[no photo]	Left Head Lamp	Faded	Refinish	Repair Required
[no photo]	Right Head Lamp	Faded	Refinish	Repair Required
[no photo]	Rear Bumper/Cover	Previous Repair	Wet Sand	Substd Dirt
[no photo]	Hood	Chipped	Touch Up	5
[no photo]	Left Qtr Panel	Dent(S) W/No Paint Dmg	PDR	1/2 To 1 Inch
[no photo]	Left Front Door	Dent(S) W/No Paint Dmg	PDR	1/2 To 1 Inch
[no photo]	Left Rear Door	Dent(S) W/ Paint Dmg	Report	1/2 To 1 Inch
[no photo]	Rear Bumper/Cover	Chipped	Touch Up	3
[no photo]	Right Front Door	Multiple Dents/No Paint Damage	PDR	2
	Bluetooth	Clear History	Remove	Removal Required
	Hood	Peeling	Report	2 To 3 Inches
	Right Interior A Pillar Trim	Loose	Repair	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.