



Approved CR

IAA Austin North
23010 Firefly Rd
Branch No 457
Florence, TX 76527
2549700575
mgr-austinnorth@iaai.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD
TRANSIT-350**
Bodystyle/Series: **Wagon XL**
Color: **White**
Mileage: **88,525
(Verified)**
Turn-in Mileage: **-**
VIN: **1FBZX2ZM8JKB43003**
Work Order/
Stock Number: **46368901**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **-**
Vehicle Grade : **Grade 3.2**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	5th	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 65 R 16

Car Tire Size - LR 225 / 65 R 16

Car Tire Size - RR 225 / 65 R 16

Car Tire Size - RF 225 / 65 R 16

LF Tires - 10/32 inch

LR Tires - 9/32 inch

RF Tires - 10/32 inch

RR Tires - 8/32 inch

Tire Brand - Front Left - YOKOHAMA

Tire Brand - Front Right - YOKOHAMA

Tire Brand - Rear Left - YOKOHAMA

Tire Brand - Rear Right - YOKOHAMA

Tire Model - LR - YK-HTX

Tire Model - LF - YK-HTX

Tire Model - RR - YK-HTX

Tire Model - RF - YK-HTX

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper Cover Upper	Multiple Scratches Light	-	3
	Right Rear Wheel	Curb Rash	-	3 To 4 Inches
	Right Rear Cargo Door	Dent(S) W/No Paint Dmg	-	1 To 2 Inches
	Left Rear Wheel	Curb Rash	-	3 To 4 Inches
	Left Fuel Door	Misaligned	-	Repair Required
	F Bumper Textured	Cracked	-	1 To 2 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel	Curb Rash	-	5 To 6 Inches
	Roof	Peeling	-	> 12 Inches
	Shifter Knob	Worn	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.