



Approved CR

IAA Spokane
3520 N Tschirley Rd
Branch No 322
Spokane, WA 99224
(509)891-2388/(855)631-9008
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 RAM
2500**
-
Bodystyle/Series: **TRADESMAN
4X4 8' BOX**
Color: **White**
Mileage: **63,454
(Verified)**
Turn-in Mileage: -
VIN: **3C7WR5AJXJG314226**
Work Order/
Stock Number: **46383687**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G632758V**
Vehicle Grade : **Grade 3.3**
Remarks: -
Announcements: -
Certification : -
Req. Prev. Repair -
Order: -



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.4 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	Cloth/Vinyl /GRAY	Rear Defroster:	No
Airbag:	-	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 275 / 70 R 18

Car Tire Size - LR 275 / 70 R 18

Car Tire Size - RR 275 / 70 R 18

Car Tire Size - RF 275 / 70 R 18

LF Tires - 6/32 inch

LR Tires - 6/32 inch

RF Tires - 7/32 inch

RR Tires - 5/32 inch

Tire Brand - Front Left - HERCULES

Tire Brand - Front Right - HERCULES

Tire Brand - Rear Left - HERCULES

Tire Brand - Rear Right - HERCULES



Tire Model - RR - Terra Trac A/T

Tire Model - RF - Terra Trac A/T

Tire Model - LR - Terra Trac A/T

Tire Model - LF - Terra Trac A/T

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Pickup Bed	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Bed Side	Dent(S) W/ Paint Dmg	-	9 To 10 Inches
	Left Bed Side	Multiple Scratches Heavy	-	3
	Left Front Fender	Dent(S) W/ Paint Dmg	-	1 To 2 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.