



Approved
CR

IAA Seattle
15801 110th Ave E
Branch No 327
Puyallup, WA 98374
(253)604-2300/(253)604-2390
WHOLESALE ASSESSMENT ONLY

Make/Model: **2008 FORD F-350**
Bodystyle/Series: **Crew Cab KING
RANCH/LARIAT/XL/XLT**
Color: **Dark Blue**
Mileage: **33,219 (Verified)**
Turn-in Mileage: **-**
VIN: **1FTWW32Y48ED58276**
Work Order/
Stock Number: **46383639**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**



Client Stock #: **G41B5379**

Vehicle Grade : **Grade 3.3**

Remarks: **-**

Announcements:

- REPAIR HISTORY NOT AVAILABLE. CONDITION UNKNOWN
- REPAIRS MAY BE NEEDED
- PARTS MAY BE MISSING
- NON GSA OWNED VEHICLE

Certification : **-**

Req. Prev. Repair **-**

Order:

Drivable: Yes

Equipment

Transmission:	-	A/C:	No
Engine:	10-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.8 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	Synthetic Leather /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	Rear Wheel Drive

Equipment

Seat Count: -

Brakes:

Disc

Additional Equipment:

Car Tire Size - LF 245 / 75 R 17

Car Tire Size - LR 245 / 75 R 17

Car Tire Size - RR 245 / 75 R 17

Car Tire Size - RF 245 / 75 R 17

LF Tires - 15/32 inch

LR Tires - 14/32 inch

RF Tires - 14/32 inch

RR Tires - 14/32 inch

Tire Brand - Front Left - YOKOHAMA

Tire Brand - Front Right - YOKOHAMA

Tire Brand - Rear Left - YOKOHAMA

Tire Brand - Rear Right - YOKOHAMA

Tire Model - RR - Geolander A/T G015


Tire Model - RF - Geolander A/T G015

Tire Model - LR - Geolander A/T G015

Tire Model - LF - Geolander A/T G015

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Windshield	Cracked	-	> 12 Inches
	Tailgate	Dent(S) W/ Paint Dmg	-	11 To 12 Inches
	Left Qtr Flare	Broken	-	Replacement Required
	Inside Bed	Multiple Scratches Heavy	-	10 Or More
	Left Front Wheel	Peeling	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.