



Approved
CR

United Auto Exchange
3710 Prescott Rd
Memphis, TN 38118
9017957634
jcraig@uaxmemphis.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020
HYUNDAI
ELANTRA
4 Door Sedan**

Bodystyle/Series: **SE 4D SEDAN
AT**

Color: **SILVER**

Mileage: **26,278
(Verified, 6
digits)**

Turn-in Mileage: **-**

VIN: **5NPD74LF0LH607057**

Work Order/
Stock Number: **000081959**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**

Client Stock #: **G133373X**

Vehicle Grade : **Grade 4.2**

Remarks: **-**

Announcements:

- DEFICIENCIES, WHEN KNOWN, HAVE BEEN NOTED IN THE ITEM DESCRIPTION
- HOWEVER, THE ABSENCE OF ANY INDICATED DEFICIENCIES
- DOES NOT MEAN THERE ARE NONE.

Certification : **Not Certified**

Req. Prev. Repair
Order: **-**



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
---------------	------------------------	------	-----

Equipment

Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Power Brakes



Additional Equipment:

ABS Brakes	Air Conditioning	Bluetooth Connection
Brake Assist System	Car Tire Size - RF tire size 195/65R15	Car Tire Size - LR tire size 195/65R15
Car Tire Size - LF tire size 195/65R15	Car Tire Size - RR tire size 195/65R15	Child Safety Locks
Collision Avoidance	Cruise Control	Cylinders - 4
Daytime Running Lights	Driver Air Bag	Dual Air Conditioning
Empty Weight - 2844 lb	Floor Mats	Front Wheel Drive
Front Wheel Drive	Independent Climate Control	Intermittent Wipers
Keyless Entry	LF Tires - 5/32 inch	LR Tires - 5/32 inch
Lane Departure System	MP3 Radio	Master Key - 1key(s)
Motor Fuel Type - Gas	Pass-Through Rear Seat	Pass. Air Bag
Power Brakes	Power Lock	Power Mirrors
Power Steering	Power Windows	RF Tires - 5/32 inch
RR Tires - 6/32 inch	Rear Defrost	Remote Trunk Release
Reverse Camera	Seat Trim - Cloth	Security System
Side Airbags - Front	Spare Tire	Steering Wheel Audio Control
Stereo - AM/FM Radio	Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg NEXEN
Tire Brand - Front Right - RF tire mfg NEXEN	Tire Brand - Rear Left - LR tire mfg NEXEN	Tire Brand - Rear Right - RR tire mfg NEXEN
Tire Pressure Monitor System	Traction Control	Transmission - Automatic Transmission
Trip Computer		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Extra Photo 6	Photo Only	Estimate Only	Unknown
	Extra Photo 7	Photo Only	Estimate Only	Unknown
	Frame	Photo Only	Estimate Only	Unknown

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Hood	Chipped	Report	4
	Left Front Door	Multiple Dents/Paint Damage	Repair	3
	Left Rear Door	Dent(S) W/ Paint Dmg	Repair	1/2 To 1 Inch

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Qtr Panel	Dent(S) W/ Paint Dmg	Repair	1/2 To 1 Inch
	Right Front Door	Dent(S) W/No Paint Dmg	PDR	Pdr-1 Dent

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.