Approved CR

IAA New Orleans East
6600 Almonaster Avenue
Branch No 432
New Orleans, LA 70126
(504) 240-2298/(504) 244-0883
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2020 DODGE DURANGO**
Bodystyle/Series:	**Sport Utility Vehicle PURSUIT AWD**
Color:	**White**
Mileage:	**1 (Unverified)**
Turn-in Mileage:	-
VIN:	**1C4RDJFG3LC431571**
Work Order/ Stock Number:	**46251410**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G624146X**
Vehicle Grade :	**Grade 1.2**
Remarks:	-
Announcements:	• salvage
Certification :	-
Req. Prev. Repair Order:	-

Drivable: No

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**No**
Airbag:	-	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**All Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Equipment

Additional Equipment:

Car Tire Size - LR 265 / 60 R 18	Car Tire Size - RR 265 / 60 R 18	Car Tire Size - RF 265 / 60 R 18
Car Tire Size - LF 265 / 60 R 18	LF Tires - 9/32 inch	LR Tires - 11/32 inch
RF Tires - 8/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - FIRESTONE
Tire Brand - Front Right - FIRESTONE	Tire Brand - Rear Left - FIRESTONE	Tire Brand - Rear Right - FIRESTONE
Tire Model - LF - Destination A/T2	Tire Model - LR - Destination A/T2	Tire Model - RF - Destination A/T2
Tire Model - RR - Destination A/T2		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Left Drip Rail	Previous Repair	-	Acceptable
	Roof	Previous Repair	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Head Lamp	Faded	-	Repair Required
	Right Qtr Panel	Multiple Scratches Light	-	2
	Rear Bumper	Scraped	-	5 To 6 Inches
	Right Front Window	Broken	-	Replacement Required
	Right Front Wheel	Curb Rash	-	1 To 2 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Wheel	Curb Rash	-	4 To 5 Inches
	Lift Gate	Chipped	-	6
	Left Qtr Panel	Multiple Scratches Light	-	2
	Left Front Fender	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Center Console	Missing	-	Replacement Required
	Right Side Curtain Air Bag	Deployed	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Door Panel	Missing	-	Replacement Required
	Left Rear Door Panel	Missing	-	Replacement Required
	Headlining	Bent	-	Replacement Required
	Left Front Window	Missing	-	Replacement Required
	Left Front Seat Cushion	Torn	-	1/2 To 1 Inch
	Steering Wheel	Worn	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Door	Dent(S) W/ Paint Dmg	-	9 To 10 Inches
	Right Head Lamp	Faded	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.