Approved CR

Dealers Auto Auction of Cincinnati, LLC
120 City Centre Drive
Cincinnati, OH 45216
513-679-7910/513-679-7913
aschoenling@dealersauto.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2020 CHEVROLET MALIBU LS**
Bodystyle/Series:	**4 Door Vehicle -**
Color:	**SILVER**
Mileage:	**32,725 (Digital)**
Turn-in Mileage:	-
VIN:	**1G1ZC5ST0LF011383**
Work Order/ Stock Number:	**0051349**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**102620I2011383**
Vehicle Grade :	**Grade 3.2**
Remarks:	-
Announcements:	• RIDE & DRIVE
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

As Is 100K Miles: NO

Equipment

Transmission:	**Continuously Variable Transmission**	A/C:	**Yes**
Engine:	**4-Cylinder Gas Turbo**	Cruise Control:	**Yes**
Engine Size:	**1.5 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**- /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**Buckets**	Drive Type:	**Front Wheel Drive**
Seat Count:	**0**	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

Automatic Headlights	Auxiliary Audio Input	Auxiliary Pwr Outlet
Backup camera and monitor	Bluetooth Connection	Brake Assist System
Car Jack	Car LF Tires - 7/32 inch	Car LR Tires - 8/32 inch
Car RF Tires - 7/32 inch	Car RR Tires - 6/32 inch	Car Tire Size - LF: P205/65R16 LR: P205/65R16 RF: P205/65R16 RR: P205/65R16 SP: SPACE SAVER
Child Safety Locks	Cylinders - 4	Daytime Running Lights
Driver Restriction Features	Driver Vanity Mirror	Electronic Stability Control
Emergency Trunk Release	First Aid Kit	Floor Mats
Front Head Air Bag	Hand Tool Kit	Ignition Key - 1key(s)
Keyless Start	Knee Air Bag	LF Tires - 7/32 inch
LR Tires - 8/32 inch	MP3 Radio	Pass-Through Rear Seat
Pass. Air Bag	Passenger Air Bag Sensor	Passenger Vanity Mirror
Power Mirrors	RF Tires - 7/32 inch	RR Tires - 6/32 inch
Rear Bench Seat	Rear Head Air Bag	Security System
Side Airbags - Front	Side Airbags - Rear	Smart Device Integration
Spare Tire - Space Saver	Spare Tire Brand - MAXXIS	Spare Tire Tread - 4/32 inch
Spare Wheel - Steel	Steering Wheel Audio Control	Telematics
Tilt Steering Wheel	Tire Brand - Front Left - FIRESTONE	Tire Brand - Front Right - FIRESTONE
Tire Brand - Rear Left - FIRESTONE	Tire Brand - Rear Right - FIRESTONE	Tire LF - 7/32 inch
Tire Pressure Monitor System	Tire RF - 7/32 inch	Tire Size - LF: P205/65R16 LR: P205/65R16 RF: P205/65R16 RR: P205/65R16 SP: SPACE SAVER
Tire Size - LF: P205/65R16 LR: P205/65R16 RF: P205/65R16 RR: P205/65R16 SP: SPACE SAVER	Wheels Front Left - Aluminium	Wheels Front Right - Aluminium
Wheels Rear Left - Aluminium	Wheels Rear Right - Aluminium	WiFi Hotspot

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 6	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 9	Photo Only	-	-
	Extra Photo 8	Photo Only	-	-

Chargeable Damages

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper/Cover	Chipped	Refinish	10 Or More
	Hood	Chipped	Touch Up	1
	Emergency Trunk Release	Broken	Replace	Replacement Required
	Right Front Door	Light Scratch	Wet Sand	1 To 2 Inches
	Right Qtr Panel	Light Scratch	Wet Sand	1 To 2 Inches
	Right Rear Door	Previous Repair	Refinish	Substandard Repair
[no photo]	Tools	Missing	Replace	Replacement Required
[no photo]	Jack Assembly (Lugg. Comp.)	Missing	Replace	Replacement Required
[no photo]	Emergency Road Kit	Missing	Replace	Replacement Required
	Rear Bumper/Cover	Light Scratch	Wet Sand	1 To 2 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.