Approved CR

IAA Seattle
15801 110th Ave E
Branch No 327
Puyallup, WA 98374
(253)604-2300/(253)604-2390
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2020 FORD POLICE INTERCEPTOR**
Bodystyle/Series:	**Sport Utility Vehicle -**
Color:	**Black**
Mileage:	**55,061 (Verified)**
Turn-in Mileage:	-
VIN:	**1FM5K8AWXLGC38446**
Work Order/ Stock Number:	**45855032**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G624758Y**
Vehicle Grade :	**Grade 0.8**
Remarks:	-
Announcements:	• JUNK TITLE • PARTS ONLY • NOT TO BE TITLED FOR HWY USE
Certification :	-
Req. Prev. Repair Order:	-

Drivable: No

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Hybrid**	Cruise Control:	**Yes**
Engine Size:	**3.3 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	-	Tilt Steering:	**Yes**
Seats:	**5th**	Drive Type:	**All Wheel Drive**

Equipment

Seat Count: -

Brakes: **Disc**

Additional Equipment:

Car Tire Size - RR 255 / 60 R 18	Car Tire Size - RF 255 / 60 R 18	Car Tire Size - LF 255 / 60 R 18
Car Tire Size - LR 255 / 60 R 18	LF Tires - 1/32 inch	LR Tires - 3/32 inch
RF Tires - 1/32 inch	RR Tires - 3/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - LF - Eagle Enforcer	Tire Model - LR - Eagle Enforcer	Tire Model - RF - Eagle Enforcer
Tire Model - RR - Eagle Enforcer		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Right Inner Qtr Panel	Kinked	-	> 12 Inches
	Right Rear Wheel Housing	Kinked	-	> 12 Inches
	Right C Pillar	Kinked	-	> 12 Inches
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Curtain Air Bag	Deployed	-	Replacement Required
	Left Front Door	Heavy Scratch	-	4 To 5 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Headlining	Burn Hole	-	> 12 Inches
	Right Rear Seat	Burn Hole	-	> 12 Inches
	Left Front Tire	Worn	-	Replacement Required
	Left Rear Tire	Worn	-	Replacement Required
	Right Front Tire	Worn	-	Replacement Required
	Right Rear Tire	Worn	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Qtr Panel	Severe Damage	-	Replacement Required
	Right Rear Door	Severe Damage	-	Replacement Required
	Right Front Door	Dent(S) W/ Paint Dmg	-	2 To 3 Inches
	Left Rear Seat	Burn Hole	-	> 12 Inches
	Moldings	Broken	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.