



Approved
CR

Akron Auto Auction
2471 Ley Drive
Akron, OH 44319
3304365819/(330) 773-3921
lbeth@akronautoauction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018
HYUNDAI
IONIQ
HYBRID
4 Door Sedan**

Bodystyle/Series: **BLUE 4D
HATCHBACK**

Color: **GRAY**

Mileage: **58,340
(Verified, 6
digits)**

Turn-in Mileage: **-**

VIN: **KMHC65LC3JU075747**

Work Order/
Stock Number: **000745857**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G130986V**

Vehicle Grade : **Grade 3.4**

AutoGrade : **3.4 - Average**


Remarks: **-**

Announcements: **-**

Certification : **Not Certified**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	1.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment

Additional Equipment:

ABS Brakes	Air Conditioning	Automatic Headlights
Bluetooth Connection	Brake Assist System	Car Tire Size - LF tire size P195/65HR15
Car Tire Size - RR tire size P195/65HR15	Car Tire Size - RF tire size P195/65HR15	Car Tire Size - LR tire size P195/65HR15
Child Safety Locks	Cruise Control	Cylinders - 4
Daytime Running Lights	Driver Air Bag	Empty Weight - 2996 lb
Engine Immobilizer	Floor Mats	Front Wheel Drive
Front Wheel Drive	HD Radio	Independent Climate Control
Intermittent Wipers	Keyless Entry	Keyless Start
LF Tires - 8/32 inch	LR Tires - 8/32 inch	MP3 Radio
Master Key - 1key(s)	Motor Fuel Type - Other	Pass-Through Rear Seat
Pass. Air Bag	Power Brakes	Power Lock
Power Mirrors	Power Steering	Power Windows
RF Tires - 8/32 inch	RR Tires - 8/32 inch	Rear Defrost
Rear Spoiler	Reverse Camera	Seat Trim - Cloth
Security System	Side Airbags - Front	Steering Wheel Audio Control
Stereo - AM/FM Radio	Tilt Steering Wheel	Tilt Wheel
Tire Pressure Monitor System	Traction Control	Transmission - Automatic Transmission
Trip Computer	Wheels Front Left - Steel	Wheels Front Right - Steel
Wheels Rear Left - Steel		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown


Non Chargeable Damages


Photo	Item	Damage	Action	Severity
	Right Qtr Panel	Photo Only	Estimate Only	Unknown
	Hood	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Left Qtr Panel	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Photo - Front	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Curb Rash	Repair	> 12 Inches
	Left Front Door	Multiple Scratches Heavy	Touch Up	3
	Left Front Fender	Multiple Scratches Heavy	Touch Up	3
	Left Rear Door	Dent(S) W/No Paint Dmg	PDR	1 To 2 Inches
	Half Liftgate Trim Panel	Missing	Replace	Replacement Required
	Hood	Chipped	Touch Up	1

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Rear Door	Multiple Scratches Heavy	Touch Up	2
	Right Qtr Panel	Multiple Dents/Paint Damage	Repair	7
	Rear Bumper	Chipped	Touch Up	3
	Roof	Multiple Dents/No Paint Damage	PDR	4
	Roof	Multiple Scratches Heavy	Touch Up	3
	Right Front Door Edge	Chipped	Touch Up	1
	Rf Mirror Cover	Gouged	Repair	1 To 2 Inches
	Right Rear Wheel Cover	Curb Rash	Repair	1/2 To 1 Inch
[no photo]	Left Front Wheel Cover	Chipped	Repair	5
[no photo]	Left Rear Wheel Cover	Chipped	Repair	6

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.