Original CR

IAA Anchorage
1446 W Mystery Ave
Branch No 372
Wasilla, AK 99654
(907)312-5580/(907)312-5680
WHOLESALE ASSESSMENT ONLY

| | |
|---|---|
| Make/Model: | **2016 FORD F-250** |
| Bodystyle/Series: | **Regular Cab XL** |
| Color: | **Blue** |
| Mileage: | **10,062 (Verified)** |
| Turn-in Mileage: | - |
| VIN: | **1FTBF2B61GED03113** |
| Work Order/ Stock Number: | **46501517** |
| Customer: | GSA Fleet Vehicle Sales<br>1800 F Street NW<br>Washington, DC 20405<br>fleetsalessupport@gsa.gov |
| Client Stock #: | **G632471S** |
| Vehicle Grade : | **Grade 3.8** |
| Remarks: | - |
| Announcements: | - |
| Certification : | - |
| Req. Prev. Repair Order: | - |



Drivable: Yes

## Equipment

| | | | |
|---|---|---|---|
| Transmission: | **Automatic Transmission** | A/C: | **No** |
| Engine: | **8-Cylinder Gas** | Cruise Control: | **Yes** |
| Engine Size: | **6.2 L** | Pwr Steering: | **Yes** |
| Roof: | **Hard Top** | Pwr Locks: | **Yes** |
| Radio: | - | Pwr Windows | **Yes** |
| Interior - Type/Color: | **Cloth Interior /GRAY** | Rear Defroster: | **No** |
| Airbag: | **Driver Side Air Bag** | Tilt Steering: | **Yes** |
| Seats: | **Bench** | Drive Type: | **4-Wheel Drive** |
| Seat Count: | - | Brakes: | **Disc** |

## Equipment

Additional Equipment:

| | | |
|---|---|---|
| Car Tire Size - RR 245 / 75 R 17 | Car Tire Size - RF 245 / 75 R 17 | Car Tire Size - LF 245 / 75 R 17 |
| Car Tire Size - LR 245 / 75 R 17 | LF Tires - 11/32 inch | LR Tires - 10/32 inch |
| RF Tires - 10/32 inch | RR Tires - 10/32 inch | Tire Brand - Front Left - GENERAL |
| Tire Brand - Front Right - GENERAL | Tire Brand - Rear Left - GENERAL | Tire Brand - Rear Right - GENERAL |
| Tire Model - LF - Grabber HTS | Tire Model - LR - Grabber HTS | Tire Model - RF - Grabber HTS |
| Tire Model - RR - Grabber HTS | | |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Right Rear Bumper/Cover | Photo Only | - | - |
|  | Photo - Dash | Photo Only | - | - |
|  | Extra Photo 1 | Photo Only | - | - |
|  | Odometer | Photo Only | - | - |
|  | Rear Seats | Photo Only | - | - |
|  | Warning - Tire Pressure | On | - | Unacceptable |
|  | Photo - Vin/Id Sticker | Photo Only | - | - |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Engine | Photo Only | - | - |
|  | Keys | Photo Only | - | - |
|  | Front Cover Center | Photo Only | - | - |
|  | Right Side Panel | Photo Only | - | - |
|  | Left Side Panel | Photo Only | - | - |
|  | Instrument Panel | Photo Only | - | - |
|  | Rear Bumper | Photo Only | - | - |
|  | Right Front Fender | Photo Only | - | - |
|  | Left Front Fender | Photo Only | - | - |
|  | Left Rear Bumper/Cover | Photo Only | - | - |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Left Front Door | Multiple Scratches Heavy | - | 3 |
|  | Right Bed Side | Dent(S) W/ Paint Dmg | - | < 1/8 Inch |
|  | Tailgate Molding | Heavy Scratch | - | 1/2 To 1 Inch |
|  | Roof | Heavy Scratch | - | 1/2 To 1 Inch |
|  | Steering Wheel | Worn | - | Replacement Required |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.