Approved CR

Dealers Auto Auction of Cincinnati, LLC
120 City Centre Drive
Cincinnati, OH 45216
513-679-7910/513-679-7913
aschoenling@dealersauto.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2017 CHEVROLET TAHOE**
Bodystyle/Series:	**Sport Utility Vehicle LS**
Color:	**GOLD**
Mileage:	**81,656 (Digital)**
Turn-in Mileage:	-
VIN:	**1GNSKAEC9HR296937**
Work Order/ Stock Number:	**0051564**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**102620I2296937**
Vehicle Grade :	**Grade 3.7**
Remarks:	-
Announcements:	• RIDE & DRIVE
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission w/ Overdrive**	A/C:	**Yes**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**5.3 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**CD Only**	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**Bench**	Drive Type:	**4-Wheel Drive**
Seat Count:	**0**	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

3rd Row Seat	Automatic Headlights	Auxiliary Audio Input
Backup camera and monitor	Bluetooth Connection	Brake Assist System
Car LF Tires - 9/32 inch	Car LR Tires - 9/32 inch	Car RF Tires - 9/32 inch
Car RR Tires - 9/32 inch	Car Tire Size - LF: P265/65R18 LR: P265/65R18 RF: P265/65R18 RR: P265/65R18 SP: FULL SIZE	Child Safety Locks
Cylinders - 8	Daytime Running Lights	Driver Adjustable Lumbar
Driver Restriction Features	Electronic Stability Control	Floor Mats
Front Head Air Bag	Front Tow Hooks	HD Radio
Heated Mirrors	Ignition Key - 2key(s)	Independent Climate Control
Intermittent Wipers	Keyless Start	LF Tires - 9/32 inch
LR Tires - 9/32 inch	Leather Steering Wheel	Limited Slip Differential
MP3 Radio	Pass-Through Rear Seat	Pass. Air Bag
Passenger Adjustable Lumbar	Passenger Air Bag Sensor	Power Driver & Passenger Seat
Power Driver Seat	Power Mirrors	Privacy Glass
RF Tires - 9/32 inch	RR Tires - 9/32 inch	Rain Sensor
Rear AC	Rear Bench Seat	Rear Head Air Bag
Rear Parking Aid	Running Board	Security System
Side Airbags - Front	Smart Device Integration	Spare Tire - Full Size
Spare Tire Brand - FIRESTONE	Spare Tire Tread - 7/32 inch	Spare Wheel - Steel
Steering Wheel Audio Control	Tilt Steering Wheel	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire LF - 9/32 inch	Tire Pressure Monitor System	Tire RF - 9/32 inch
Tire Size - LF: P265/65R18 LR: P265/65R18 RF: P265/65R18 RR: P265/65R18 SP: FULL SIZE	Tire Size - LF: P265/65R18 LR: P265/65R18 RF: P265/65R18 RR: P265/65R18 SP: FULL SIZE	Tow Hitch
Transmission - Automatic Transmission w/ Overdrive	Wheels Front Left - Aluminium	Wheels Front Right - Aluminium
Wheels Rear Left - Aluminium	Wheels Rear Right - Aluminium	WiFi Hotspot


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 7	Photo Only	-	-
	Extra Photo 9	Photo Only	-	-
	Extra Photo 8	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Miscellaneous	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper/Cover	Multiple Scratches Heavy	Refinish	10 Or More
	Left Front Door	Chipped	Refinish	10 Or More
	Left Rear Door	Light Scratch	Wet Sand	1 To 2 Inches
	Rear Bumper/Cover	Light Scratch	Wet Sand	1 To 2 Inches
	Lift Gate	Light Scratch	Wet Sand	1 To 2 Inches
	Right Rear Door	Light Scratch	Wet Sand	1 To 2 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.