Approved CR

IAA San Diego
2380 Britannia Blvd
Branch No 116
San Diego, CA 92154
(619) 710-2866/(619) 710-2878
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2024 DODGE DURANGO**
Bodystyle/Series:	**Sport Utility Vehicle PURSUIT AWD**
Color:	**White**
Mileage:	**100,814 (Verified)**
Turn-in Mileage:	-
VIN:	**1C4RDJFG6RC182627**
Work Order/ Stock Number:	**46440795**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G62B2219**
Vehicle Grade :	**Grade 3.2**
Remarks:	-
Announcements:	• CONDITION UNKNOWN • SALVAGE STAMPED CERTIFICATE TO OBTAIN TITLE WILL BE ISSUED • REAR DOORS / WINDOWS INOPERABLE MAY BE INOPERABLE • FORMER POLICE VEHICLE
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**

Equipment

Engine:	**6-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**All Wheel Drive**
Seat Count:	-	Brakes:	**Disc**


Additional Equipment:

Car Tire Size - LF 255 / 60 R 18	Car Tire Size - LR 255 / 60 R 18	Car Tire Size - RR 255 / 60 R 18
Car Tire Size - RF 255 / 60 R 18	LF Tires - 10/32 inch	LR Tires - 10/32 inch
RF Tires - 10/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - FIRESTONE
Tire Brand - Front Right - FIRESTONE	Tire Brand - Rear Left - FIRESTONE	Tire Brand - Rear Right - FIRESTONE
Tire Model - RR - Firehawk Pursuit Awt	Tire Model - RF - Firehawk Pursuit Awt	Tire Model - LR - Firehawk Pursuit Awt
Tire Model - LF - Firehawk Pursuit Awt		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Aftermarket Accessory	Aftermarket	-	Acceptable
	Cargo Box	Aftermarket	-	Acceptable
	Center Console	Aftermarket	-	Acceptable
	Led Flashlight	Aftermarket	-	Acceptable
	Left Drip Rail	Previous Repair	-	Acceptable
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Steering Wheel	Worn	-	Replacement Required
	Left Front Wheel	Curb Rash	-	3 To 4 Inches
	Front Bumper	Scraped	-	2 To 3 Inches
	Left Rear Wheel	Curb Rash	-	> 12 Inches
	Hitchplate Cover	Missing	-	Replacement Required
	Right Front Door	Chipped	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	4 To 5 Inches
	Overall Vehicle	De-Identify	-	Removal Required
	Hood	Misaligned	-	Repair Required
	Right Rear Wheel	Curb Rash	-	5 To 6 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.