



Approved CR

IAA Macon
2200 Trade Ave.
Branch No 734
Macon, GA 31217
(478) 314-0031/(478) 314-0040
WHOLESALE ASSESSMENT ONLY

Make/Model: **2023
CHEVROLET
EXPRESS
PASSENGER**

Bodystyle/Series: **Van RWD
2500
REGULAR**

Color: **White**

Mileage: **119,997
(Verified)**

Turn-in Mileage: **-**

VIN: **1GAWGEFP0P1106758**

Work Order/
Stock Number: **46278521**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G430721Z**

Vehicle Grade : **Grade 3.8**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	4.3 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Vinyl Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment


Additional Equipment:

Car Tire Size - RR 245 / 75 R 16	Car Tire Size - RF 245 / 75 R 16	Car Tire Size - LF 245 / 75 R 16
Car Tire Size - LR 245 / 75 R 16	LF Tires - 9/32 inch	LR Tires - 3/32 inch
RF Tires - 9/32 inch	RR Tires - 6/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - IRONMAN	Tire Brand - Rear Right - GOODYEAR
Tire Model - LF - Wrangler Workhorse HT	Tire Model - LR - All Country A/T2	Tire Model - RF - Wrangler Workhorse HT
Tire Model - RR - Wrangler Workhorse HT		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
-------	------	--------	--------	----------

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Dutch Cargo Door	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Left Rear Tire	Worn	-	Replacement Required
	Left Front Door	Heavy Scratch	-	1 To 2 Inches
	Front Ls Panel	Chipped	-	2
	Left Rear Wheel	Curb Rash	-	1/2 To 1 Inch
	Rear Ls Panel	Heavy Scratch	-	1/2 To 1 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Chipped	-	10 Or More
	Hood	Chipped	-	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.