Approved
CR

Orlando Auto Auction
4636 W. Colonial Dr
Orlando, FL 32808
(407) 299-3904/(407) 294-6982
david.orlandoautoauction@gmail.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2020 FORD F-150 POLICE RESPOND**
Bodystyle/Series:	**Crew Cab -**
Color:	**WHITE**
Mileage:	**88,324 (Digital)**
Turn-in Mileage:	-
VIN:	**1FTEW1P45LKF21761**
Work Order/ Stock Number:	**0318742**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G622887X**
Vehicle Grade :	**Grade 3.2**
Remarks:	-
Announcements:	• FORMER POLICE UNIT. DEFICIENCIES, WHEN KNOWN, • HAVE BEEN NOTED IN THE ITEM DESCRIPTION; HOWEVER, • THE ABSENCE OF ANY INDICATED DEFICIENCIES DOES • NOT MEAN THERE ARE NONE.
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission w/ Overdrive**	A/C:	**Yes**
Engine:	**6-Cylinder Gas Turbo**	Cruise Control:	**Yes**


Equipment

Engine Size:	**3.5 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	- /**GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**Bench**	Drive Type:	**4-Wheel Drive**
Seat Count:	**0**	Brakes:	**Power Brakes**

Additional Equipment:

4th Passenger Door	Automatic Headlights	Auxiliary Pwr Outlet
Backup camera and monitor	Bedliner	Bluetooth Connection
Brake Assist System	Car LF Tires - 5/32 inch	Car LR Tires - 5/32 inch
Car RF Tires - 5/32 inch	Car RR Tires - 4/32 inch	Car Tire Size - LF: LT275/65SR18 LR: LT275/65SR18 RF: LT275/65SR18 RR: LT275/65SR18
Child Safety Locks	Cylinders - 6	Daytime Running Lights
Driver Adjustable Lumbar	Driver Restriction Features	Electronic Stability Control
Engine Immobilizer	Front Head Air Bag	Front Tow Hooks
Heated Mirrors	Ignition Key - 1key(s)	Independent Climate Control
Intermittent Wipers	Keyless Entry - Left	LF Tires - 5/32 inch
LR Tires - 5/32 inch	Limited Slip Differential	Misc. Special Features - Passenger Third Door, Airbag Disconnect Switch
Pass. Air Bag	Passenger Air Bag Sensor	Passenger Vanity Mirror
Power Driver Seat	Power Mirrors	Privacy Glass
RF Tires - 5/32 inch	RR Tires - 4/32 inch	Rear Bench Seat
Rear Head Air Bag	Security System	Side Airbags - Front
Smart Device Integration	Spray In Bedliner	Steering Wheel Audio Control
Telematics	Tilt Steering Wheel	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire LF - 5/32 inch	Tire Pressure Monitor System	Tire RF - 5/32 inch
Tire Size - LF: LT275/65SR18 LR: LT275/65SR18 RF: LT275/65SR18 RR: LT275/65SR18	Tire Size - LF: LT275/65SR18 LR: LT275/65SR18 RF: LT275/65SR18 RR: LT275/65SR18	Tow Hitch
Transmission - Automatic Transmission w/ Overdrive	Transmission - Automatic Transmission	Trip Computer
Turn Signal Mirrors	Wheels Front Left - Aluminium	Wheels Front Right - Aluminium
Wheels Rear Left - Aluminium	Wheels Rear Right - Aluminium	


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Extra Photo 8	Photo Only	-	-
	Extra Photo 9	Photo Only	-	-
	Miscellaneous	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Antenna Mast	Broken	Replace	Replacement Required
	Front Bumper/Cover	Rust	Replace	Severe Damage
	Engine	Noise	Check and Advise	Repair Required
	Frame	Rust	Refinish	Naaa Acceptable
	Roof	Peeling	Refinish	5 To 6 Inches
	Left Front Seat Back	Worn	Replace	Replacement Required
	Hood	Bug Damage	Refinish	Repair Required
	Left Front Wheel	Corrosion	Refinish	> 12 Inches
	Left Bed Side	Dent(S) W/ Paint Dmg	Repair	4 To 5 Inches
	Left Rear Wheel	Corrosion	Refinish	> 12 Inches
	Bedliner	Aftermarket	Remove	Removal Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper/Cover	Rust	Repair	5 To 6 Inches
	Tailgate	Misaligned	Check and Advise	Repair Required
	Right Rear Wheel	Corrosion	Refinish	> 12 Inches
	Right Front Wheel	Corrosion	Refinish	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.