Approved
CR

Orlando Auto Auction
4636 W. Colonial Dr
Orlando, FL 32808
(407) 299-3904/(407) 294-6982
david.orlandoautoauction@gmail.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2016 CHEVROLET COLORADO 4WD**
Bodystyle/Series:	**Crew Cab Z71**
Color:	**GRAY**
Mileage:	**78,883 (Digital)**
Turn-in Mileage:	-
VIN:	**1GCGTDE36G1268135**
Work Order/ Stock Number:	**0318739**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G611610S**
Vehicle Grade :	**Grade 3.5**
Remarks:	-
Announcements:	• TPMS LIGHT. DEFICIENCIES, WHEN KNOWN, HAVE BEEN • NOTED IN THE ITEM DESCRIPTION; HOWEVER, THE • ABSENCE OF ANY INDICATED DEFICIENCIES DOES NOT • MEAN THERE ARE NONE.
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**6-Cylinder Gas**	Cruise Control:	**Yes**

Equipment

Engine Size:	**3.6 L**	Pwr Steering:	**No**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**- /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**Buckets**	Drive Type:	**4-Wheel Drive**
Seat Count:	**0**	Brakes:	**Power Brakes**


Additional Equipment:

Auxiliary Audio Input	Backup camera and monitor	Bluetooth Connection
Car LF Tires - 9/32 inch	Car LR Tires - 9/32 inch	Car RF Tires - 9/32 inch
Car RR Tires - 9/32 inch	Car Tire Size - LF: P255/65R17 LR: P255/65R17 RF: P255/65R17 RR: P255/65R17 SP: FULL SIZE	Cylinders - 6
Daytime Running Lights	Driver Adjustable Lumbar	Driver Illuminated Vanity Mirr
Driver Vanity Mirror	Electrochromic Rearview Mirror	Electronic Stability Control
Engine Immobilizer	Floor Mats	Fog Lamps
Front Head Air Bag	Front Reading Lamps	Front Tow Hooks
Heated Front Seat(s)	Ignition Key - 1key(s)	Independent Climate Control
Keyless Entry - Left	Keyless Start	LF Tires - 9/32 inch
LR Tires - 9/32 inch	Leather Steering Wheel	Limited Slip Differential
MP3 Radio	Pass. Air Bag	Passenger Adjustable Lumbar
Passenger Air Bag Sensor	Passenger Illuminated Vanity M	Passenger Vanity Mirror
Power Driver & Passenger Seat	Power Driver Seat	Power Mirrors
RF Tires - 9/32 inch	RR Tires - 9/32 inch	Rear Bench Seat
Rear Head Air Bag	Running Board	Security System
Side Airbags - Front	Sliding Rear Glass	Smart Device Integration
Spare Tire - Full Size	Spare Wheel - Steel	Steering Wheel Audio Control
Telematics	Tilt Steering Wheel	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire LF - 9/32 inch	Tire Pressure Monitor System	Tire RF - 9/32 inch
Tire Size - LF: P255/65R17 LR: P255/65R17 RF: P255/65R17 RR: P255/65R17 SP: FULL SIZE	Tire Size - LF: P255/65R17 LR: P255/65R17 RF: P255/65R17 RR: P255/65R17 SP: FULL SIZE	Wheels Front Left - Aluminium
Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium	Wheels Rear Right - Aluminium

Equipment

WiFi Hotspot XM Radio


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 8	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 9	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Seat Cushion	Torn	Repair	5 To 6 Inches
	Front Center Armrest	Broken	Replace	Replacement Required
	Roof	Peeling	Refinish	> 12 Inches
	Frame	Rust	Refinish	Naaa Acceptable
	Right Running Board	Corrosion	Replace	10 To 11 Inches
	Right Front Fender	Peeling	Refinish	> 12 Inches
	Right Bed Side	Previous Repair	Light Compound	Buffable
	Right Bed Side	Heavy Scratch	Touch Up	1 To 2 Inches
	Left Running Board	Rust	Refinish	11 To 12 Inches
	Left Front Fender	Peeling	Refinish	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Peeling	Refinish	> 12 Inches
	Right Head Lamp	Faded	Repair	Repair Required
	Left Head Lamp	Faded	Repair	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.